

デフィーリンクアドバンスコントロールユニット取扱説明書 Defi-Link ADVANCE Control Unit Operation Manual

DF07703

### 日本国内でご購入の場合は2ページから40ページをお読みください。

このたびは、当社製品をお買い上げいただきまして、誠にありがとうございます。お客様・取付業者様ともに、ご使用の前に取扱説明書を全て必ずお読みいただき、正しいお取り扱い方法でご愛用いただけますようお願い申し上げます。

なお、本品の装着に関する事故や弊害につきましては、いかなる場合に おいても、当社は一切責任を負いかねますので、あらかじめご了承いただ けますようお願い申し上げます。

※英語の部分は国内では無効です。

【Web サイト】https://www.nippon-seiki.co.jp/defi/

【電話番号】(0258)24-5221

【受付時間】10:00~12:00、13:00~17:00(土・日、祝日、当社休日を除く平日)

### English section is from P.41to P.84.

Thank you very much for purchasing our product. Before installing and using the product, please read this manual thoroughly. All sections are for customers and installation personnels. After installation, please keep this manual for future reference.

Defi will not be held responsible for accidents or damages related to installation of this product.

※ Japanese section is effective only in Japan.

[Web site] http://www.defi-shop.com/



# もくじ Contents **歩くじ Contents ・・・・・・・・・** ■安全・取り扱いに関するご注意【必ずお読みください】・2 **国**ラインナップ・・・・・・・・・・・・・8 ☑仕様・・・・・・・・・・・・・・・・10 日構成部品・各部名称・寸法・・・・・・・・・ 11 **6**取付方法・・・・・・・・・・・・・・・・ 14 **口**使用方法・・・・・・・・・・・・・・・・・21 **13**トラブルシューティング・・・・・・・・・・34 **日**補修パーツ・オプションパーツ ・・・・・・・ 37 □保守・点検・保証・アフターサービス・・・・・・・ 38 1 Safety Warning [Please read carefully.] • • • • • 41 3 List of Products • • • • • • • • • • • • • • • 48 4 Specification • • • • • • • • • • • • • • • • • • 50 5 Parts List/Part Names/Dimensions • • • • • • • 51 6 Installation • • • • • • • • • • • • • • • 54 7 Operation • • • • • • • • • • • • • • • • • 61 8 Troubleshooting • • • • • • • • • • • • • • • 75 9 Repair parts/Optional parts • • • • • • • • • • 78 10 Maintenance & Check/Warranty & Servicing • • • • • 79



## ■安全・取り扱いに関するご注意【必ずお読みください】

本製品は ADVANCE シリーズのメーター・ディスプレイの動作に必要な製品です。本製品のみでは機能しません。メーター・ディスプレイとともにご使用ください。また、メーター・ディスプレイの取り付け時にはそちらの取扱説明書と合わせてお読みください。

本製品は車両情報を表示する製品です。本製品をお取り付けの前に取扱説明書及び取り付ける車両のメーカーが発行している整備解説書、配線図に示されている内容や安全に関する注意事項をよくお読みいただき、十分に理解された上でお取り付けいただけますようお願い申し上げます。また、本製品(及び本製品の取り付けられている車)を他の人に貸し出したり譲渡する場合は、スタートガイドと保証書を必ずお渡しください。

なお、最新のエンジンコンピュータ配線図は当社 Web サイトに掲載しておりますので、ご確認ください。

本書では、取り扱いを誤った場合などの危険の程度を「危険」「警告」「注意」の3つのレベルで分類しています。また、本製品を安全に正しくお使いいただくために必ず行っていただきたい事項と、守っていただきたい事項を「確認」として分類しています。内容をよくお読みいただき、十分に理解された上でお取り付けください。

<u> </u>	取り扱いを誤った場合、死亡、又は重傷を負うことがあり、
/11/尼陕	かつその切迫度合いが高いことが想定される場合。
⚠警告	取り扱いを誤った場合、死亡、又は重傷を負う可能性が想定
	される場合。
<b></b> 注意	取り扱いを誤った場合、傷害を負う危険が想定される場合、
/!! 注思	または物的損害の発生が想定される場合。
確認 「必ず行っていただきたい事」、「必ず守っていただきたし	
四性 配	を示しています。

### 注意内容の性質表示

<u> </u>	⚠注意 (警告を含む)をしなければならない記号です。
○禁止	○は、行為を禁止する記号です。(絶対にしてはいけない事です。)
● 強制	●は、行為を指示する記号です。(必ず行っていただくことです。)



### ■取付作業をする前に(取り付け業者様へ)

### 危険

- ●作業を行う時は必ず車が動き出さないような措置をし、エンジンを停止してから行ってください。作業中に車が動き出したり、火災の原因になり大変危険です。
- ●配線作業中は必ずキーシリンダーから鍵を抜き、バッテリーのマイナス(-) ターミナルを外してください。ショート事故による火災の原因となり大変危険です。
- △シートベルトやエアバックなどの安全装置や、エンジン、ステアリング、ブレーキなどの走行性能と直接関係する部位のハーネスの加工時および配線の接続時(ネジの脱着など)は誤配線に十分注意してください。車両不具合による事故や火災の原因となり大変危険です。
- ●配線の接続はハンダ付けを行うか、エレクトロタップかギボシを使用し、接続部の絶縁を必ず行ってください。また、配線に衝撃やテンションがかかるところは、緩衝材やコルゲートチューブなどで保護してください。ショート事故による火災の原因となり大変危険です。
- ●電源配線時、電源ハーネスに断線がないか、または断線しかかっていないか確認してください。ショート事故による火災の原因となり大変危険です。
- ●電源配線時、IGN ハーネス接続ラインの車両側に30A以下のヒューズがあることを確認してください。30Aを超えるヒューズの場合、ショート故障の際に溶断せず火災の原因となり大変危険です。
- ●ヒューズが切れた場合は速やかに製品の使用を中止してください。続けて使用するとショート事故による火災の原因となり大変危険です。また、車両の故障や事故の原因となります。
- ●電源ハーネスのヒューズを交換する場合は、必ず規定容量のヒューズをで使用ください。規定容量を超えるヒューズを使用した場合、火災の原因となり大変危険です。
- ○製品は水のかかる場所、湿気の多い場所には取り付けないでください。ショート事故による火災の原因となり大変危険です。
- ●製品が故障したり誤動作した場合は速やかに製品の使用を中止してください。続けて使用すると車両の故障や事故の原因となります。



# ▲ 警告

- ●取付箇所・取付方法は慎重に検討し、絶対に脱落しないようにしてください。 特に安全装置や運転の妨げになる位置に製品を取り付けないでください。誤った取付箇所・取付方法は、製品の脱落や車両破損の原因、運転の妨げとなります。
- ○本製品を絶対に改造や分解しないでください。保証の対象外となるだけでなく故障や事故の原因となります。

◇XXXV 改造·分解

◎エンジン停止直後は絶対に作業を行わないでください。エンジン停止直後は エンジンや排気管が非常に高温になっており、火傷を負う可能性があります。

- ●必ず既存の配線がショートおよび断線しないように本製品の配線を行ってください。また、車速・エンジン回転数信号の配線の際は、以下の順で配線作業を行ってください。手順を誤ると車両のコントローラーなどを破壊する恐れがあります。
  - 1. 最初にアドバンスコントロールユニットの電源配線を行ってください。
  - 2. イグニッションキー ON 時にアドバンスコントロールユニットの電源確認マークが点灯することを確認してください。
  - 3. バッテリーのマイナス (ー)端子を再度外し、車速・エンジン回転数信号の配線作業を行ってください。
- ○配線作業中にハーネスを切断する場合、複数のハーネスをまとめて切断しないでください。必ず単線毎に切断してください。ハーネスをまとめて切断すると車両のコントローラーなどを破壊する恐れがあります。
- ○作業中は幼児・子供等を近づけないでください。部品等が外れて飲み込む等の恐れがあります。
- ○乗員保護装置(エアバッグ等)の作動に影響を及ぼす場所に取り付けないでください。保護装置作動時にケガの恐れがあります。

# ∧ 注意

- 12V 仕様車専用です。12V 車以外には取り付けないでください。
- ●使用しない配線は絶縁テープなどで完全に絶縁してください。また、取り付け時に外したり、ゆるめた部品やコネクター、新たに配線したものなどは必ず正しく組みつけ、固定してください。
- ○本製品に過大な力をかけたり、ぶつけたり、落としたりしないでください。 故障の原因となります。



- ○本製品の端子などに必要以上の力を加えないでください。破損の原因となります。
  ○本製品付属のハーネス以外で配線をしないでください。
- △車体やネジ部などに、配線をはさみ込まないようにしてください。故障の原因となります。
- △ハーネスは点火信号や無線、HID ユニットのハーネスなどのノイズの発生し そうな場所を避けて配線してください。点火系などのノイズはメーター誤動 作の原因となります。
- ▲アドバンスコントロールユニットに無線機や携帯電話等電波を発する機器が 触れないように設置してください。誤動作の原因となります。
- ○ハーネスは、エンジン、排気管、過給機付近には配線しないでください。ハーネスの破損、溶断の原因になります。
- △エンジンルーム内で配線を分岐する際は、防水処理を確実に行ってください。
- ○メーターは前面に傾けないでください。オイルが漏れる 90°可能性があります。Aの角度は90度以上でなくてはなり ません。
- ▲センサーを取り付ける際は、センサー近くのハーネス部分を曲げないように 取り付けてください。
- ●ハンダ付けで火傷をしたり、配線・部品の端面・尖った部分等に当たり手を切傷することがないように手袋を着用してください。
- ◎アドバンスコントロールユニットは、水のかかる場所、湿気やほこりの多い場所、ヒーターの吹き出し口やその周辺には取り付けないでください。
- ●センサーは熱のこもらない場所、及び水のかからない場所を選んで取り付けてください。センサー破損の原因となります。
- ●サンシールドを使用する場合は、フロントガラスと製品の間に置くようにして製品が日陰になるようにしてください。
- △清掃するときは、電源を切り、乾いた柔らかい布で拭いてください。汚れを 落とす場合は、中性洗剤に浸してよく絞った布で拭いてください。有機溶剤 (ベンジン、シンナーなど)、酸・アルカリ類は使用しないでください。
- ○コード、特にコネクター部を強く引っ張らないでください。 破損の原因となります。コネクターを抜く際は、ロックを を確実に押しながら抜いてください。
- ○インストルメントパネルの助手席側及びセンターに本製品やメーターを埋め 込まないでください。車両の保安基準に適合しません。



### 確認

- ●取り付けは必ず本書に従ってください。
- ^ハバッテリーのマイナス(-)ターミナルを外すと、メモリー機能を持ったオー ディオや時計などの記憶内容が消去される物があります。作業終了後、それ ぞれの取扱説明書に従って設定し直してください。
- ●取付作業が終了しましたら、スタートガイド、保証書、残りの部品、パッケー ジは必ずお客様にお渡しください。
- △指針が真下から動いている場合がありますが、異常ではありません。通電す れば、正常動作します。
- ●純正部品の取り付け、取り外しに際しては、カーメーカー発行の整備書を確 認してください。
- ●電源配線前に、分岐する車両配線の電圧を確認してください。配線後、電源 ハーネスのコネクター側で再度電圧を確認してから製品に接続してください。
- Λナビゲーションシステムやカーテレビを取り付けている場合は、それら本体 やアンテナ、モニター、ハーネス類からできるだけ離して本製品の配線、取 り付けを行ってください。近付けたり、ハーネスを一緒に東ねたりするとテ レビ表示 (VHF) に影響を与える場合があります。
- △取付作業の際に純正部品等が破損、紛失しても、当社は一切の責任を負いか ねますのであらかじめご了承ください。

# ■取り扱いに関して(お客様・取り付け業者様へ)

### ⚠ 警告

- ●本製品はお買い上げいただいた販売店またはディーラーで取り付けてくださ い。個人でお取り付けされた場合、保証の対象外となります。
- ○本製品を絶対に改造や分解しないでください。保証の対象外 となるだけでなく故障や事故の原因となります。

- ○走行中は安全のため本製品の情報の確認は最小限の時間にとどめ、長時間凝 視しないでください。前方不注意による事故の原因となり大変危険です。
- ◇「表示がでない」などの故障状態や、「水などがかかった」「煙が出た」「変な 匂いがする」などの異常な状態では使用しないでください。万一そのような



状態が発生しましたら、すみやかに販売店、取り付け店にご連絡ください。 そのままご使用になりますと、事故や火災の原因となり大変危険です。

- ●操作は車を停止して行ってください。
- ●幼児・子供等がスイッチやその他の部品を飲み込まないようにインパネ等にしっかりと固定してください。
- ADVANCE ZD のタイムアタック計測はクローズドコース専用機能です。 一般道では絶対に使用しないでください。

# 注意

- △本製品の使用、または故障により生じた直接・間接の損害につきましては、 当社は一切の責任を負いかねますのであらかじめご了承ください。
- ◎コード、特にコネクター部を強く引っ張らないでください。破損の原因となります。コネクターを抜く際は、ロックを確実に押しながら抜いてください。

# 確認

- △旧 Defi-Link システムとリンクさせることはできません。
- ●製品の表示は参考値です。純正メーターの指示で運転してください。
- ○同一表示(機種)のメーターは同時に接続できません。
  - (例:ターボ計を2つ接続など)
- △対応気筒数は1・2・3・4・5・6・8 気筒の4 サイクルです。ディーゼル車 には取り付けできません。
- △電源・信号の配線については車種別接続ガイドを併せてご覧ください。 最新の情報はホームページの車種別接続ガイドをご参照ください。
- ▲アイドリングストップ車の場合、アイドリングストップ時のバッテリー電圧 の降下によりエンジン始動復帰時に製品の電源がオフ/オンする場合があり ますが、製品の異常ではありません。
- ●取付後も定期的に点検を実施し、十分注意してご使用ください。使用環境や 条件等によって耐久性が落ちる場合があります。
- ●廃棄する時は、各自治体の指示に従ってください。



### 2特長

- アドバンスシステム (双方向通信) 採用
- アドバンスシリーズのメーター・ディスプレイを最大 7 台まで集中操作
- 夜間照明付き(ホワイト)リモコンスイッチにより手元操作が可能
- ADVANCE ZD をリンクすることでメーターの照明を自動調節
- 2 種類から選択可能なオープニングモードとエンディングモードで演出
- 2 台目以降のメーター追加は、メーター間の接続とセンサーからアドバンス コントロールユニットに配線するのみ
- 自己診断機能により、断線・ショート・通信エラーを診断し、ワーニング 表示でお知らせ
- ワーニング値(任意)を設定、ワーニング表示と同期してブザー音でも警告(ブザー音は ON/OFF の設定 が可能)
- 走行データ(走行中のピーク値、ワーニング値)を最大 3 分間記録し、走 行後に再生可能
- メーター・ディスプレイに専用の取付キットを標準装備
- 燃圧センサーとターボセンサーを接続することで燃圧計もしくは ADVANCE ZD に差圧表示可能

### **国**ラインナップ

製品名	品番
デフィーリンクアドバンスコントロールユニット	DF07703

### ■ ADVANCE CR・RS メーター Φ 52 シリーズ

機種名	表示範囲	CR 白文字板	CR 黒文字板	RS 黒文字板
ターボ計 2.0	-100kPa ∼ +200kPa	DF07801	DF07802	DF13501
インマニ計(※1)	-100kPa ∼ +20kPa			DF13601
油圧計	0 ∼ 1000kPa	DF08101	DF08102	DF13701
燃圧計	0 ∼ 600kPa			DF13801
油温計	50 ∼ 150℃	DF08301	DF08302	DF13901
水温計	20 ∼ 120℃	DF08401	DF08402	DF14001
排気温度計	200 ∼ 1100°C			DF14101



# ■ ADVANCE CR メーター Φ 60 シリーズ

機種名	表示範囲	白文字板	黒文字板
ターボ計 2.0	-100kPa ∼ +200kPa	DF08601	DF08602
ターボ計 1.2	-100kPa ∼ +120kPa	DF08701	DF08702
インマニ計(※1)	-100kPa ∼ +20kPa	DF08801	DF08802
油圧計	0 ∼ 1000kPa	DF08901	DF08902
燃圧計	0 ∼ 600kPa	DF09001	DF09002
油温計	50 ∼ 150℃	DF09101	DF09102
水温計	20 ~ 120°C	DF09201	DF09202
排気温度計	200 ∼ 1100℃	DF09301	DF09302
タコメーター	0 ∼ 9000rpm	DF09403	DF09404

### ■ ADVANCE BF・A1 メーター Φ 60 シリーズ

機種名	表示範囲	BF ホワイト モデル	BF アンバー レッド モデル	BF ブルー モデル	A1
ターボ計 3.0	-100kPa ∼ +300kPa	DF14701	DF14702	DF14703	DF14901
ターボ計 2.0	-100kPa ∼ +200kPa	DF09901	DF09902	DF09903	DF14801、02( * 2)
ターボ計 1.2	-100kPa ∼ +120kPa	DF10001	DF10002	DF10003	
インマニ計(※1)	-100kPa ∼ +20kPa	DF10101	DF10102	DF10103	
油圧計	0 ∼ 1000kPa	DF10201	DF10202	DF10203	DF15001
燃圧計	0 ∼ 600kPa	DF10301	DF10302	DF10303	DF15101
油温計	50 ∼ 150℃	DF10401	DF10402	DF10403	DF15201
水温計	20 ∼ 120℃	DF10501	DF10502	DF10503	DF15301、02( ** 2)
排気温度計	200 ∼ 1100°C	DF10601	DF10602	DF10603	DF15401
タコメーター	0 ∼ 9000rpm	DF10704	DF10705	DF10706	

# ■ ADVANCE メーター Φ 80 シリーズ

機種名	表示範囲	BF ホワイト モデル	BF アンバー レッド モデル	BF ブルー モデル	RS	A1
タコメーター	0 ∼ 9000rpm	DF10901	DF10902	DF10903	DF14201	
タコメーター	0 ∼ 11000rpm	DF11001	DF11002	DF11003	DF14301	DF15501

製品名	品番
デフィーリンクメーターアドバンスズィーディー	DF09701



- ▲本製品は ADVANCE シリーズのメーター・ディスプレイの動作に必要な製品です。本製品のみでは機能しません。メーター・ディスプレイとともにで使用ください。また、メーター・ディスプレイの取り付け時にはそちらの取扱説明書と合わせてお読みください。
- ※1:インマニ計はインテークマニホールドプレッシャー計を省略したものです。
- ※2: DF14802、DF15302 には、センサー・センサーハーネス・センサー取付関連部品が同梱されていません。

### 4仕様

■電源電圧 10V ~ 16V DC(12V 車専用)

■消費電流 メーター・ディスプレイ7台接続時の最大値

+B線 2A(IGN ON 時) / 5mA(IGN OFF 時)

ILM線 800mA

■照明色 アドバンスコントロールユニット電源確認マーク:青

スイッチユニット・文字:白

スイッチユニット差圧表示インジケーター:青

■対応気筒数 1.2.3.4.5.6.8 (4 サイクル)

■温度範囲(すべて湿度80%以下とする)

	保存温度範囲	使用温度範囲
CR·RS·BF·A1·ZD	-30 ∼ +80°C	-20 ∼ +60°C
アドバンスコントロールユニット	-30 ∼ +80°C	-20 ∼ +60°C
スイッチユニット	-30 ∼ +80°C	-20 ∼ +60°C
ターボセンサー	-30 ∼ +100°C	-30 ∼ +80°C
圧力センサー	-30 ∼ +140°C	-30 ∼ +120°C
温度センサー	-30 ∼ +150°C	-20 ∼ +150°C
排気温度センサー	-30 ~ +130℃	-30 ~ +130℃


※センサーのコネクター部は 105℃以下

※排気温度センサーはセンシング部分は除く




# 5構成部品・各部名称・寸法

# 5 -1. 構成部品





### **13**-2. アドバンスコントロールユニットの各部名称・寸法 (mm)




- ●ハーネス接続用コネクター
- ①スイッチユニット(白)
- ②車速・エンジン回転数信号ハーネス(青) 2: オープニング・エンディング
- ③排気温度センサーハーネス(黒)
- ④水温ヤンサーハーネス(ピンク)
- ⑤油温センサーハーネス(赤)
- ⑥燃圧センサーハーネス(赤)
- ⑦油圧センサーハーネス(黒)
- ⑧ターボ / インマニセンサーハーネス (水色)
- ⑨電源ハーネス (ベージュ)
- ⑩メーターハーネス(白)⑪メーターハーネス(白)

△メーターハーネスは⑩と⑪のどちらにもつなぐことができます。出荷時は ⑪のメスコネクターに端子間ショート保護用のオスコネクターが差し込ん であります。⑪を使わない場合はオスコネクターは外さないでください。 印を使う場合はオスコネクターのロックを押して外してからメーターハー ネスを接続してください。


1: ワーニングブザー ON/OFF 切替



### ■ -3. スイッチユニットの各部名称・寸法 (mm)



#### ●スイッチユニット背面



#### ●ボタンとスライドスイッチについて

操作は全て3個のボタンと1個のスライドスイッチで行ないます。スライドスイッチの上・中・下段の位置で各ボタンの役割が変わります。

#### ●スライドスイッチ

本書ではスライドスイッチの位置を以下のように表記します。

REAL(上): リアルモード操作用 **上 REAL**〉

PLAY(中): 記録したデータを再生するときの操作用 **中 PLAY** 

SET(下): 設定をするときの操作用 **SET** 

### ●ボタン

各ボタンにはスライドスイッチの位置と役割に合わせた上・中・下の3段のマークがあります。本書ではスライドスイッチの位置に合わせ、各ボタンを以下のように表記します。 左

左ボタン:上から順に **全・REC** または **全・PLAY** または **全! WARN.SET** ボタン 中央ボタン:上から順に **中・PEAK** または **中・▽** ボタン 右ボタン:上から順に **右 DIM/RESET** または **右 ▶** または **右** ボタン




### 6取付方法

#### 確認

●メーター・ディスプレイの取扱説明書も一緒にお読みください。メーター・ディスプレイ・各センサーの取付方法はメーターの取扱説明書に記載されています。

#### 6 -1. 配線図全体



メーターハーネスは 2 箇所ある METER OUTPUT のコネクターのどちらにも接続できます。アドバンスコントロールユニット 1 台にメーターと ZD を合わせて 7 台まで接続可能です。また、それぞれのラインに振り分けて最大 7 台まで接続することも可能です(例:片方に 7 台つなぐともう一方は 0 台 )。

○同一表示 (機種)のメーターは同時に接続できません (例:ターボ計を2台)。 ただし、ZD を複数台同時に接続することは可能です。



### 6 -2. 全体の流れ

- 内容物を確認します。
   ⇒構成部品、各メーターの取扱説明書参照
- 2. 取り付けに必要な部品 (アタッチメント類)を確認し、準備します。 ⇒各メーターの取扱説明書の各センサー取付方法参照
  - ●アタッチメント類は別途市販品をご購入ください。
- 3. 車両の電源 (+B、GND、IGN、ILM) 取り位置とセンサー取付位置を確認します。
- 4. バッテリーのマイナス(-)ターミナルを外します。
- 5. 電源ハーネスを車両に配線します。
- ⇒6-3.ハンダ付けのやり方、エレクトロタップの使い方参照

# ∧警 告

- ○IGN は ACC(アクセサリー電源)に配線しないでください。IGN を ACC に配線 すると車両の故障や事故の原因となります。
- 6. 電源ハーネスをアドバンスコントロールユニットのコネクターに接続します。一旦バッテリーのマイナスターミナルを接続、イグニッションを ON にしアドバンスコントロールユニットの前面にある電源確認マークが点灯することを確認してください。

#### 確認

△電源が正常に配線されていないと LED は点灯しません。点灯しない場合は 再度配線をで確認ください。



- 7. バッテリーのマイナスターミナルを外し、各センサーを取り付けます。⇒各メーターの取扱説明書の各センサー取付方法参照
- 8. 各センサーにセンサーハーネスを接続し、アドバンスコントロールユニット に接続します。
- 9. 配線・接続確認のために、一旦メーターハーネスを使用してメーター・ZD とアドバンスコントロールユニットを接続します。メーターはハーネスの みの仮接続のため、ホルダーに入れて固定しないでください。

# ▲ 注意


- ◇ METER OUTPUT のコネクターを 1 箇所しか使用しない場合は、ショート防止のため保護用のオスコネクターは外さないでください。
- 10. バッテリーのマイナスターミナルを接続します。
- 11. イグニッションを ON にし、電源確認マークが点灯することを確認してください。電源ハーネスが正常に配線されている場合、アドバンスコントロールユニットの電源確認マークが青く点灯します。また、車両のイルミを ON にし、CR メーターの照明が点灯、または BF メーターが減光、または ZD のスイッチ照明が点灯することを確認してください。
- ●電源確認マークが点灯しない場合:電源が取れていない →イグニッションを一旦 OFF にし、電源ハーネスの配線をご確認ください。
- ●メーター内のワーニング LED が点滅している、またはワーニング LED とピーク LED が同時点滅している場合:センサーやセンサーハーネスの配線がショートやオープンになっている、またはメーターとアドバンスコントロールユニット間のどこかで通信が出来ない
  - ⇒2 -3-2. オープン・ショートシリアル通信のエラー表示参照
- →イグニッションを一旦 OFF にし、センサー、センサーハーネスの配線をご 確認ください。



# **魚警告**

- ●配線に抜けなどの異常が見当たらない場合は、製品が故障している可能性があるので、速やかに製品を外し検査依頼をしてください。車両にダメージを与える可能性があります。
  - ⇒**10**保守・点検・保証・アフターサービス参照
- 12. イグニッションを OFF にします。
- 13. 一度メーターからメーターハーネスを外し、メーターホルダーを使用して メーターを取付位置に設置します。しっかりと取り付けられていることを 確認し、メーターハーネスを接続します。
  - ⇒各メーターの取扱説明書のメーターホルダーと取付金の取付方法参照
- 14. スイッチユニットをアドバンスコントロールユニットに接続し、任意の位置にスイッチユニットを両面テープで固定します。固定する部分の汚れは 拭き取っておいてください。
  - ⇒5 -3. スイッチユニットの各部名称参照
- 15. アドバンスコントロールユニットのディップスイッチ 2 個を設定します。
  - ●ディップスイッチ 1: ブザーの ON/OFF を設定します。
  - ●ディップスイッチ 2: イグニッションを ON/OFF にしてオープニング・エンディングモードを A・B の 2 種類から選びます。
  - ⇒ **5** -2. アドバンスコントロールユニットの各部名称・**7** -6-2. ワーニングブザー ON/OFF の変更・**7** -2-1. オープニング・エンディングモードの変更参照
- 16. 設定が終了したらアドバンスコントロールユニット付属の六角ナットと ネジ、市販の取付金具を使用して固定します。





アドバンスコントロールユニット

# 確認

- ○本製品及びメーターは防水構造ではありませんので足元や水のかかりそうな場所には設置しないでください。
- ●付属のネジで固定するため、取付金は厚さ 3mm 以下のものをご用意ください。
- ○付属のネジ以外は使用しないでください。アドバンスコントロールユニットの内部を損傷させる恐れがあります。
- ●設定は後で変更可能です。アドバンスコントロールユニット固定後もディップスイッチが操作できるように取り付けてください。

### 17.取付最終確認をします。

# ▲ 警告

- ●最終仕上げとして以下の項目を必ず実施してください。さもないと重大な事故が発生する恐れがあります。
- □取り付けた配管が確実に接続され、配管の差し忘れや誤配線、及び液漏れ、 排気漏れがないか確認してください。



- □ハーネスやアドバンスコントロールユニットなどがエンジンルーム内で作動 装置(ラジエターファン、スロットルボディなど)と干渉していないか確 認してください。
- □センサー本体やハーネスなどが運転の妨げにならないように、確実に固定されているか、もう一度確認してください。
- □メーター取り付けの際に取り外した車両側の内装、ハーネス類が元通りに戻されているか、エンジンコンピュータなどのコネクタの挿し忘れがないか、もう一度確認してください。

# ▲ 警告

- ●作業終了後は必ず、運転席やエンジンルームに何もないことを確認してください。運転席の足下に使用した工具類などがあると、ブレーキペダルの下に挟まり、ブレーキ操作が出来なくなるなどの恐れがあり大変危険です。また、エンジンルームに使用した工具があるとエンジン破損の恐れがあり大変危険です。
- □バッテリーのマイナスターミナルをはずれないようにしっかりと取り付け、 ボンネットを確実に閉めてください。

以上で取り付けは終了です。

#### 確認


●アドバンスコントロールユニット・スイッチユニットには透明の保護フィルムが貼ってあります。で使用前にはがしてください。はがさずにで使用になると、経年劣化によりのりが変質し、フィルムがはがれなくなる場合があります。



## 6 -3. ハンダ付けのやり方・エレクトロタップの使用方法

# ▲ 注意

- ●ハンダ付けで火傷をしたり、配線にあたり手を切傷することがないように、 手袋を着用してください。
- ●配線する際は、出来るだけハンダ付けで行い、接触不良を起こさないように確実に配線してください。
- ●ハンダ付けのやり方



●エレクトロタップの使用方法





左右のツメがロックしたことを確認 ※プライヤーを使用してください。 ラジオペンチでは加締め不良にな る場合があります。

### 確認

- ●製品に付属のエレクトロタップは芯線径 0.3 ~ 0.75mm 用です。必ず指定範囲内でご使用ください。
- ◎エレクトロタップの指定範囲より太い芯線には使用しないでください。芯線が断線し、発熱の恐れがあります。



## 2使用方法

使用方法の説明では、ボタンの押し方が「押す」方法と「長押し」方法の2種 類出てきます。「押す」の場合は1秒未満ボタンを押してください。「長押し」 の場合は1秒以上ボタンを押してください。

### **2**-1. 各種設定・動作確認

- 1. イグニッションを ON し、アドバンスコントロールユニットの電源確認マークが点灯していることを確認してください。
  - ⇒6取付方法参照
- 2.オープニングモードが行われることを確認してください。
  - ⇒7 -2. オープニング・エンディングモード参照
- メーター・ZD にオープン・ショートのエラー表示が出ていないことを確認してください。
  - ⇒7 -3-2. オープン・ショート・シリアル通信のエラー表示参照
  - ●エラー表示が出ている場合
    - →イグニッションを一旦 OFF にし、エラー表示が出ているセンサー及び センサーハーネスをご確認ください。
- 4. タコメーターを取り付けている場合は気筒数と応答性を設定してください。
- △ ZD を取り付けている場合は ZD のシステムセットアップモードでタコメーターの設定を行います。 ZD の設定は接続されているタコメーターにも適用されます。 ZD の操作方法は ZD の取扱説明書をご参照ください。
  - タコメーターも ZD も取り付けていない場合は次のステップへ
  - ⇒**7** -4. 気筒数設定モード・**7** -5. タコメーター広答性設定モード参照
- 5. 各メーター・ZD のワーニング値と各 CR・RS メーターの照明色を設定してください。メーターと ZD のワーニング値は一度の操作で同時に設定されます。
  - ⇒7 -6-3. 照明色の変更参照
- 6. メーター・ZD が正常に動作することを確認してください。確認ができたら 設定は終わりです。

# ▲ 警告

●設定・確認は必ず車を停止した状態で行ってください。



### 2-2.オープニング・エンディングモード

イグニッションを ON するとメーター・ZD がオープニングモードを行います。 また、全ての状態において、イグニッションを OFF するとメーター・ZD がエ ンディングモードを行い、モード終了後にアドバンスコントロールユニットと メーターの電源が切れます。

### 確認

△設定の途中で OFF にすると設定内容は保存されません。

●電源ハーネスが正常に配線されている場合、オープニングモード開始時から アドバンスコントロールユニットの電源確認マークが青く点灯します。点 灯していない場合や点滅している場合はイグニッションを一旦 OFF にし、 配線をご確認ください。

⇒6取付方法参昭

### 2-2-1. オープニング・エンディングモードの変更

アドバンスコントロールユニットに付いているオープニング・エンディング モード切替用のディップスイッチ 2 をスライドさせることで、オープニング / エンディングモードをシンプルな A タイプとこだわりの B タイプの 2 種類か ら選ぶことができます。

A・B タイプともにメーター指針の動きやデジタル表示、その他にもピーク &ワーニング LED、文字板リング照明、文字板照明の点灯・点滅・色の変化、 ZD のシーケンシャルインジケーターなどによる演出があります。切り替えて 実際の演出をご確認ください。

●モードの変更はイグニッション OFF 時に行ってください。接続している全てのメーター・ZD のモードが切り替わります。



### 72 -3. リアルモード (スライドスイッチ位置: LE REAL)

オープニングモード終了後にリアルモードへ移行します。リアルモード中は車両情報をリアルタイムに表示します。


### 7 -3-1. ワーニング

設定したワーニング値以上で当該メーター内のワーニング LED が点灯します。 油圧・燃圧は設定したワーニング値以下でワーニング LED が点灯します。ZD は当該表示が反転します。このとき、ワーニングブザー設定を ON にしている 場合はワーニングブザーが鳴ります。

### 2 -3-2. オープン・ショート・シリアル通信のエラー表示

センサーがオープン、またはショートしている場合は当該メーターのワーニング LED が点滅します。 ZD はエラーメッセージを表示します。 一度、オープンかショートのエラー表示が出ると、イグニッションを OFF にするまで点滅が続きます。油圧および燃圧のショートメッセージはショートしている間だけ表示します。

メーター・ZD とアドバンスコントロールユニット間で通信ができなくなった場合は、シリアル通信エラーが表示され、ワーニングとピーク LED が同時に点滅します。



●エラーが表示された場合は速やかにイグニッションを OFF にし、センサー や配線を確認してください。原因がわからない場合は、販売店または取り 付けたお店に検査を依頼してください。



#### 7 -3-3. 照明

#### [ADVANCE CR·RS メーター]

車両のイルミスイッチに連動して点灯/消灯します。

また、リアルモード・レックモード・プレイモード中に**看 DIM/RESET**)ボタン を数回押すと、車両のイルミ ON 時に照明を消すことができます。5回中1回 消灯します。(イルミキャンセル)

#### 【ADVANCE BF・A1 メーター】

リアルモード・レックモード・プレイモード中に「**⑤DIM/RESET**)ボタンを押すと、明るさが調整できます。車両のイルミスイッチに連動して昼から夜のモードに切り替わり、昼5段階、夜5段階の独立した照明の明るさ調整ができます。夜間モード時に「**⑤DIM/RESET**)ボタンを数回押すと、昼間の最高の明るさにできます。(イルミキャンセル)

#### [ADVANCE ZD]

ZD は調光センサーを搭載しており、AUTO(自動調光)と MANUAL(手動設定)を選択することができます。AUTO を選択すると外の明るさに合わせて自動で表示の明るさが調整されます。

また、メーターとZDを接続し、調光設定をAUTOにすることにより、CR・RSメーターおよびスイッチユニットの照明の ON/OFF は自動切替となり、BF・A1メーターの照明は自動調光となります。

#### 7 -3-4. 差圧表示

ターボ計と燃圧計を取り付けている場合に、燃圧計及び ZD で燃圧とイン テークマニホールド圧の差を表示することが可能です。(ZD の場合は燃圧センサーとターボセンサーのみでも表示可。)差圧表示中はスイッチユニットの DIFFERENTIAL PRESSURE(差圧) インジケーター(青色)が点灯します。 リアルモードの他に、レックモードのときに差圧表示ができます。



燃圧の差圧表示について
一般的な電子燃料噴射制御車では、
燃圧はプレッシャーレギュレーター
という装置により、インテークマニ
ホールド圧に対して燃圧が一定にな
るように設定されています。
左図で燃圧を 300kPa で設定した場
合、差圧表示を行わない燃圧計では、
ブースト 100kPa の時 400kPa を表示します。
差圧表示を行うと、300kPa

と表示します。

- 1. スライドスイッチを **上 REAL** に合わせます。
- 2. 

  中●PEAK)ボタンと

  古 DIM/RESET)ボタンを同時に押すと燃圧計の表示が差圧表示に変わり、スイッチユニットの差圧表示インジケーターが点灯します。差圧表示を解除したい場合も同様に

  「中●PEAK)ボタンと

  「右 DIM/RESET)ボタンを押します。

### **17 -4. 気筒数設定モード** (スライドスイッチ位置: **TS SET** ))

タコメーターを取り付けた場合に、気筒数の設定をするモードです。 初期値:4 気筒

- △ ZD を取り付けている場合は ZD のシステムセットアップモードでタコメーターの設定を行います。 ZD の設定は接続されているタコメーターにも適用されます。 ZD の操作方法は ZD の取扱説明書をご参照ください。
- 1. スライドスイッチを**下 SET** )に合わせます。
- 2. **②IWARN.SET**)ボタンを長押しすると気筒数設定モードに移行し、タコメーターのワーニング LED とピーク LED が交互に点滅します。 ZD を取り付けている場合は ZD のシステムセットアップモードに移行し、 LED は点滅しません。また、タコメーターが接続されていない場合は気筒数設定モードには移行しません。



- ★ ボタンを押すと気筒数が8→6→5→4→3→2→1と変わります。1 気筒であれば 1000rpm を指示、4 気筒であれば 4000rpm、8 気筒であれば 8000rpm を指示します。車両の気筒数に合わせて数字を設定してください。
- 4. 設定終了後スライドスイッチを**上 REAL**) または 中 PLAY に戻してください。

### **7 -5. タコメーター応答性設定モード**(スライドスイッチ位置:**下 SET**))

タコメーターを取り付けている場合にタコメーターの応答性を設定するモードです。3 種類の中から選ぶ事ができます。

初期値:ポジション1

A ZD を取り付けている場合は ZD のシステムセットアップモードでタコメーターの設定を行います。 ZD の設定は接続されているタコメーターにも適用されます。 ZD の操作方法は ZD の取扱説明書をご参照ください。

指針の動きを見ながらお好みのポジションに設定してください。

ポジション 1	応答性:早い	1000rpm
ポジション 2	応答性:中間	2000rpm
ポジション 3	応答性:遅い	3000rpm

- 1. スライドスイッチを**下 SET** に合わせます。
- 2. (五! WARN.SET) ボタンを長押しし、気筒数設定モードに移行します。タコメーターのワーニング LED とピーク LED が交互に点滅します。
  - ZD を取り付けている場合は ZD のシステムセットアップモードに移行し、
  - LED は点滅しません。また、タコメーターが接続されていない場合は気筒数設定モード、タコメーター応答性設定モードには移行しません。



を指示、ポジション 3 であれば 3000rpm を指示します。

5. スライドスイッチを**上 REAL**〉または**中 PLAY**〉に戻してください。

#### **72 -6. 設定モード** (スライドスイッチ位置: **下 SET** ))

任意のワーニング値を設定することで、その値以上になったとき(油圧・燃圧の場合はその値以下になったとき)に当該メーター内のワーニング LED が点灯します。 ZD を取り付けている場合は、 ZD にワーニング設定画面が表示されます。メーターと ZD のワーニング値は一度で同時に設定されます。 また、各 CR メーター・RS メーターの照明色を変更することができます。 BF メーター・A1 メーター・ZD は照明色の変更はできません。

#### ■ワーニング初期値一覧

			設定	範囲	
メーター	ワーニング初期値	単位	最小値	最大値	点灯条件
ターボ 3.0	166.7	kPa	-100	300	設定値以上
ターボ 2.0/1.2	100	kPa	-100	200	設定値以上
インマニ	10	kPa	-100	200	設定値以上
タコメーター	7000	rpm	300	11000	設定値以上
油圧	120	kPa	0	1000	設定値以下
燃圧	150	kPa	0	600	設定値以下
油温	125	℃	0	150	設定値以上
水温	105	°C	0	150	設定値以上
排気温度	850	°C	0	1100	設定値以上

●車の種類やコンディションによってはワーニング初期値以下(油圧・燃圧は初期値以上)でも車両にダメージが加わる場合がありますので、取付時にお店に相談し、設定値を検討してください。

### ☑ -6-1. ワーニング値の設定

- 1. スライドスイッチを**下 SET** に合わせます。
- 2. **左!WARN,SET**)ボタンを押すと設定モードに移行します。
- 3. **左!WARN.SET** ボタンを押して設定する機種を選択します。



	選択機種	未選択機種
CR・RS メーター	ワーニング LED 点滅 文字板照明高輝度点灯	ワーニング LED 消灯 文字板照明低輝度点灯
	(車両イルミ ON 時)	(車両イルミ ON 時)
BF•A1	ワーニング LED 点滅	ワーニング LED 消灯
メーター	文字板照明高輝度点灯	文字板照明低輝度点灯
ZD	反転表示	反転しない

▲ CR·RS メーターと ZD を取り付け、ZD の調光設定を AUTO (自動調光) にしている場合、車両のイルミスイッチ ON/OFF に関わらず、CR·RS メーターの照明は自動で ON/OFF されます。明るい場所で設定すると CR·RS メーターの照明が点灯しない場合があるため、暗い場所に移動するか、ZD の調光センサー部分に手をかざすなどして光を遮断してください。

接続されていない機種は選択されません。選択される順番は以下の通りです。

ターボ計 (2.0 または 1.2) とインマニ計が両方接続されている場合は、ターボ計 (2.0 または 1.2) の設定値がインマニ計の設定値となります。2 台で別の値を設定することはできません。ターボ計 2.0 とターボ計 1.2 の場合はターボ計 2.0 が優先されます。

○同一表示のメーターは同時に接続できません(例:ターボ計2.0を2台)。

5. スライドスイッチを**上 REAL**〉または**中 PLAY**〉に戻してください。

### 2 -6-2. ワーニングブザー ON/OFF の変更

アドバンスコントロールユニットに付いているディップスイッチ 1: ブザーの ON/OFF 切替スイッチをスライドさせることでワーニング発生時のブザーの ON/OFF を設定することができます。スイッチ操作音は OFF できません。



- **④** ON/OFF の変更は IGN OFF 時に行ってください。
- △ ZD のワーニングブザー設定は ZD で行います。ZD の取扱説明書をご参照ください。

#### 7 -6-3. 照明色の変更

CR メーター・RS メーターの照明色を変更することができます。BF メーター・A1 メーター・ZD は照明色の変更はできません。

- 1. スライドスイッチを **下 SET** )に合わせます。
- 2. **(君!WARN.SET**)ボタンを押すと設定モードに移行します。
- 3. **左!WARN,SET** ボタンを押して設定するメーターを選択します。
- 4 昭明色を変更したいメーターが選択された状態で、中 ▼ ボタンと

看 ▲ ボタンを同時に押すと照明色が変わります。(車両のイルミスイッチを ON にしてください。)

CR 白文字板: ブルー ⇔ アンバーレッド CR 里文字板: ホワイト ⇔ アンバーレッド

RS 黒文字板: クラシックグリーン ⇔ クラシックホワイト (電球色)

- 5. スライドスイッチを**上 REAL**〉または**中 PLAY**〉に戻してください。

### 2-6-4. ターボ計 (2.0 または 1.2)・インマニ計のオフセット調整

ターボ計はイグニッション ON の状態で 0kPa を指しますが、センサーの特性により、まれに指針が 0 の位置から少しずれている場合があります。その場合は指針の位置をオフセット調整することができます。

- 1. スライドスイッチを**下 SET** に合わせます。
- 2. **左!WARN,SET** ボタンを押すと設定モードに移行します。



- 3. **左!WARN.SET** ボタンを押して調整したいターボ計を選択します。
- 4. **(五!WARN.SET**) ボタンを**長押し**すると、ピッという音と同時に調整が完了します。(指針はワーニング値を示しています。)
- 5. スライドスイッチを**上 REAL**〉または**中 PLAY**〉に戻してください。

## **7. リアルピークモード** (スライドスイッチ位置: **LI REAL**))

それまでの走行・アイドリング時の最大値をリアルモード中に表示するモードです。油圧・燃圧は最大値と最小値を切替表示します。リセットするとその時点からのピーク値を表示します。差圧表示をしている場合でも、燃圧計には燃圧のピーク値が表示されます。

### 油圧・燃圧センサーを接続していない場合

- 1. スライドスイッチを**上 REAL** に合わせます。
- 2. (中・PEAK) ボタンを押すとリアルピークモードに移行します。 リアルピークモード中はピーク LED が点灯します。
- 3. **中●PEAK**)ボタンを押すとリアルモードに戻ります。

#### 油圧・燃圧センサーを接続している場合

- 1. スライドスイッチを **上 REAL** に合わせます。
- 2. (★●PEAK) ボタンを押すとリアルピークモード (ハイピーク) に移行し、全てのメーターが最大値を表示します。リアルピークモード (ハイピーク) 中はピーク LED が点灯します。
- 3. ハイピーク表示中に (中●PEAK) ボタンを押すとリアルピークモード (ローピーク) に移行し、油圧計および燃圧計は最小値、それ以外のメーターは 最大値を表示します。リアルピークモード (ローピーク) 中はピーク LED が点灯します。
- 4. **中●PEAK** ボタンを押すとリアルモードに戻ります。

### **17 -8. リアルピークリセットモード** (スライドスイッチ位置: **LREAL**))

それまでの走行・アイドリング時の最大値(油圧・燃圧は最大値と最小値)を リセットするモードです。



- 1. スライドスイッチを**上 REAL**〉に合わせます。
- (□●PEAK)ボタンを押すとリアルピークモードに移行します。リアルピークモード中はピーク LED が点灯します。
- 3. リアルピークモード中に**全 DIM/RESET**)ボタンを押すと、ピーク LED が点滅しピーク値がリセットされます。リセット後はリアルモードに戻ります。ローピークとハイピークどちらの表示のときも最大値と最小値の両方が同時にリセットされます。

### **7-9. レックモード** (スライドスイッチ位置: **LREAL**))

各メーターの走行データを最大 3 分間記録するモードです。レックモード中はイルミキャンセルと差圧表示切替が可能です。

- 1. スライドスイッチを **上 REAL** )に合わせます。
- 2. **垣●REC** ボタンを押すとレックモードに移行し、記録を開始します。レックモード中はピーク LED が点滅します。
- 3. (五●REC) ボタンを押すと記録を終了し、リアルモードに戻ります。または 記録開始から3分経過するとリアルモードに戻ります。

⇒**7** -3-3. 照明・**7** -3-4. 差圧表示参照

### **17-10. レックピークモード** (スライドスイッチ位置: **LIREAL**))

記録を開始した時点からの最大値をレック中に表示するモードです。油圧・燃 圧は最大値と最小値を切替表示します。差圧表示をしている場合でも、燃圧計 には燃圧のピーク値が表示されます。

油圧・燃圧センサーを接続していない場合

- 1. レックモード中に **Φ●PEAK**)ボタンを押すとレックピークモードに移行します。 レックピークモード中はピーク LED が点灯します。
- 2. PEAK)ボタンを押すとレックモードに戻ります。また、 左 REC)ボタンを押すとリアルモードに戻ります。記録開始から3分経過するとリアルモードに戻ります。



油圧・燃圧センサーを接続している場合

- レックモード中に(由●PEAK)ボタンを押すとレックピークモード (ハイピーク) に移行し、全てのメーターが最大値を表示します。レックピークモード (ハイピーク) 中はピーク LED が点灯します。
- 2.ハイピーク表示中に PEAK) ボタンを押すとレックピークモード (ローピーク) に移行し、油圧計および燃圧計は最小値、それ以外のメーターは最大値を表示します。レックピークモード (ローピーク) 中はピーク LED が点灯します。
- 3. (申●PEAK) ボタンを押すとレックモードに戻ります。また、 (左●REC) ボタンを押すとリアルモードに戻ります。記録開始から3分経過するとリアルモードに戻ります。

### **7 -11. プレイモード** (スライドスイッチ位置: 中 PLAY))

記録されているデータを再生するモードです。一時停止、コマ送り、早送り、 巻き戻し等も可能です。プレイモード中はイルミキャンセルが可能です。

#### ⇒7 -3-3. 照明参照

- 1. スライドスイッチを中 PLAY〉に合わせます。
- 2. ⟨五►PLAY⟩ ボタンを押すとプレイモードに移行し、記録されているデータを再生します。プレイモード中はピーク LED が点滅します。
- 3. 再生中に **左▶PLAY**)ボタンを押すと再生を終了し、リアルモードに戻ります。または記録データが終了するとリアルモードに戻ります。

#### 🛮 -11-1. 再生中の操作

- ・一時停止中に(看 ▷▷)ボタンを押すとコマ送り、(看 ▷▷)ボタンを 長押しすると早送りになります。
- ・一時停止中に**左▶PLAY** ボタンを押すと再生に戻ります。

### **7 -12. プレイピークモード**(スライドスイッチ:中 PLAY))

レック中に記録されたデータの中の最大値をプレイ中に表示するモードです。



油圧・燃圧は最大値と最小値を切替表示します。プレイピークモード中もデー タ再生は進みます。

油圧・燃圧センサーを接続していない場合

- 1. スライドスイッチを中 PLAY に合わせます。
- 2. ⟨五►PLAY⟩ ボタンを押すとプレイモードに移行し、データを再生します。 プレイモード中はピーク LED が点滅します。
- 3. 再生中にスライドスイッチを**上REAL**)に合わせます。(一時停止中でも可)
- 4. **Φ PEAK** ボタンを押すと記録データ中のピーク値を表示します。
- 5. **⊕ PEAK**)ボタンを押すとデータの再生に戻ります。またはスライドスイッチを**申 PLAY**)に合わせ、**を PLAY**)ボタンを**長押し**するとリアルモードに戻ります。

油圧・燃圧センサーを接続している場合

- 1. スライドスイッチを中 PLAY に合わせます。
- 2. **⟨互▶PLAY**⟩ ボタンを押すとプレイモードに移行し、データを再生します。 プレイモード中はピーク LED が点滅します。
- 3. 再生中にスライドスイッチを **上 REAL** )に合わせます。(一時停止中でも可)
- 4. ●●PEAK)ボタンを押すとプレイピークモード (ハイピーク) に移行し、 記録データ中の最大値を表示します。
- 5.ハイピーク表示中に 中●PEAK) ボタンを押すとプレイピークモード (ロー ピーク) に移行し、油圧計・燃圧計は記録データ中の最小値、それ以外は 最大値を表示します。
- 6. (田●PEAK) ボタンを押すとデータの再生に戻ります。またはスライドスイッチを 田 PLAY) に合わせ、 (国トPLAY) ボタンを長押しするとリアルモードに戻ります。

### ■リアルピーク・レックピーク・プレイピークの違い

リアルピーク	レックピーク	プレイピーク
リアルモード	レックモード	プレイモード
全モードのピーク値	レックモードで記録された データ中のピーク値	
全モード中	レックモード中	
リアルピーク	レック開始時に オートリセットされる	
	リアルモード 全モードのピーク値 全モード中	リアルモード     レックモード       全モードのピーク値     データ中のクライン・ファック・ファック・ファック・ファック・ファック・ファック・ファック・ファック



# **8**トラブルシューティング

# ∧ 警告

- ●異常を感じたら、必ず点検をしてください。さもないと、重大な事故が発生する恐れがあります。
- ●使用中、または設定・操作の段階でトラブルが発生した場合、下表を参考に確認してください。あてはまる項目がない場合、または対処をしても改善されない場合は、取り付けたお店・販売店にご相談ください。

症状	考えられる原因	対処方法
○動作しない。	○電源ハーネスの配線が間	○取付方法に基づいて、+ B、IGN、
○電源が入らない。	違っている。	GND の配線を確認してください。
○アドバンスコント	○電源ハーネスのヒューズが	○配線を確認後、ヒューズを交換し
ロールユニットの	切れている。	てください。
電源確認マークが	○エレクトロタップのロック	○エレクトロタップの配線部分を
点灯しない。	が閉まっていない、または	確認してください。
	接触不良を起こしている。	
○アドバンスコント	○配線のどこかにショートや	○取付方法に基づいて、配線とメー
ロールユニットの	オープンなどの問題がある。	ターを確認してください。原因
電源確認マークが	またはメーターに異常があ	がわからない場合は販売店また
点滅する。	る。	は取り付けたお店に検査を依頼
		してください。
○メーターのワーニン	○センサーやセンサーハーネ	○取付方法に基づいて、センサー、
グ LED が点滅する。	スにショートやオープンな	センサーハーネスを確認してく
	どの問題がある。または	ださい。原因がわからない場合
	メーターとアドバンスコン	は販売店または取り付けたお店
	トロールユニット間で通信	に検査を依頼してください。
	ができない。	



症状	考えられる原因	対処方法
○イルミを ON しても	○ ILM の配線が間違っている。	○取付方法に基づいて、ILM の配線
CR/RS の照明が点灯	○エレクトロタップのロック	を確認してください。
しない。または BF/	が閉まっていない、または	○エレクトロタップの配線部分を
A1 の照明が減光し	接触不良を起こしている。	確認してください。
ない。	○イルミキャンセルになって	○使用方法に基づいて、イルミキャ
	いる。	ンセルを解除してください。
	○ ZD の調光設定が AUTO で	○ ZD の調光設定を MANUAL に変
	周囲が明るい。	更するか、暗い場所に移動して
		ください。
○エンディングモード	○ +B の配線が間違っている。	○取付方法に基づいて、+ B の配
を行わない。		線を確認してください。
		○エレクトロタップの +B の配線部
		分を確認してください。
		○電源の配線を確認のうえ、販売店
		または弊社お客様相談室にご相
		談ください。
○取り付け前の無通電	○製品の運搬中にメーターの	○ステッピングモーター固有の特
状態で、指針が真下	指針が動いた。	性で、無通電の状態でメーター
からずれている。		に軽い衝撃が加わると指針が動
		く場合があります。製品を動作
		させてから、イグニッションキー
		を OFF したときに指針が真下
		に戻ることを確認してください。
		真下に戻らない場合は販売店ま
		たは弊社お客様相談室にご相談
		ください。



症状	考えられる原因	対処方法
○エンジン回転数が正	○エンジン回転数信号の配線	○車種別接続ガイドに基づいて、配
常に表示されない。	が間違っている。	線を確認してください。
	○気筒数設定が間違っている。	○タコメーターの取扱説明書、車
		速、エンジン回転信号ハーネス
		の配線方法に従って配線確認を
		してください。
		○ご使用方法をご覧になり、気筒数
		設定を確認してください。
○純正メーターより指	○純正のタコメーターは実際	○純正のタコメーターとの差が最
示値が少し低い。	のエンジン回転数より最大	大で 10% 程度か確認してくだ
	で 10% 程度高い場合がある。	さい。本メーターは精度を最重
		視しているため、実際の値に対
		しほとんど誤差はありません。
		10% 程度であれば正常です。大
		きく異なる場合は気筒数設定を
		確認してください。
○シリアルエラー表示	○メーターとアドバンスコン	○配線方法に基づいて、メーター
が出る。	トロールユニット間で通信	ハーネスを確認してください。
	ができない。	原因がわからない場合は、販売
		店または取り付けたお店に検査
		を依頼してください。
○取り付けているメー	○圧力センサー(ターボ・油	○センサーが故障している場合は
ターが全てシリア	圧・燃圧センサー)の1つ	交換する必要があります。販売
ルエラーを表示す	以上がショートしている。	店または取り付けたお店に検査
る。		を依頼してください。



# **回補修パーツ・オプションパーツ** AD=ADVACE SYSTEM 専用

品番	補修パーツ品名
PDF07702H	AD 電源ハーネス (1m)
PDF07707H	AD メーターハーネス(0.25m)
PDF07710H	AD メーターハーネス(2m)
PDF07807G	AD メーターホルダー (52mm)
PDF08606G	AD メーターホルダー (60mm)
PDF07809G	AD メーター & ZD 付属品
PDF07812G	AD レギュラーポジションベゼル (52mm)
PDF08607G	AD レギュラーポジションベゼル (60mm)
PDF06503S	ターボセンサー
PDF00703S	圧力センサー
PDF00903S	温度センサー
PDF01103S	排気温度センサー
PDF01105G	排気温度センサーフィッティング
PDF06505H	ターボセンサーハーネス (2.5m)
PDF08105H	AD 油圧センサーハーネス(3m)
PDF06603H	燃圧センサーハーネス (2.5m)
PDF05602H	油温センサーハーネス (3m)
PDF05603H	水温センサーハーネス (3m)
PDF06803H	排気温度センサーハーネス (2.5m)
PDF09705H	AD 車速・エンジン回転数信号ハーネス (2m)
PDF05005G	管ヒューズ(4A) 2ヶ入り
品番	オプションパーツ品名
PDF07708H	AD メーターハーネス(0.5m)
PDF07709H	AD メーターハーネス(1m)
PDF06002H	ターボセンサー延長ハーネス (1m)
PDF00707H	圧力センサー延長ハーネス (2m)
PDF00906H	温度センサー延長ハーネス (2m)
PDF01107H	排気温度センサー延長ハーネス (2m)
DF09601	アドバンスインジケーター
DF09501	フィッティングキット

※パーツの詳細は Web サイトまたはお客様相談室にてご確認ください。



#### □保守・点検・保証・アフターサービス

#### ■保証書・保証規程について

本製品には本書とは別に保証書が入っております。また、保証書の裏面に保証規程を記載しております。本製品は保証規程の内容に従って保証されています。よくお読みになり、記入事項をで確認の上、大切に保管してください。保証書の提示がない場合は、保証期間内であっても保証対象外となります。

#### ■保証期間

保証期間はご購入から**1年**です。購入時、ご購入いただいた販売店が保証書に記載されていることをご確認ください。詳細は保証規程をご覧ください。

- △本製品を使用されて発生した違反、事故等に関するもの、誤配線等、本製品の製造不良以外による車両トラブルについては一切責任を負いかねます。
- ○危険ですのでご自身では修理しないでください。保証の対象外となるだけでなく、故障・事故の原因となります。

#### ■補修用性能部品の最低保有期間

当社は本製品の補修用性能部品を製造打ち切り後3年間保有しております。 (性能部品とはその製品の機能を保持するために必要な部品です)

#### ■検査依頼について

取り付けた製品の調子がおかしい、または動作がおかしくなったと感じた場合は、お買い上げいただいた販売店に検査をご依頼ください。Defi製品は車両への取付・配線作業が発生するため、お客様からの直接の検査ご依頼は受け付けておりません。検査・修理は Defi 製品の販売店にご依頼くださいますようお願いいたします。

引っ越しや販売店の閉店等の理由により、お買い上げいただいた販売店に行く ことができない場合はお近くの Defi 製品取扱店にで依頼いただくか、Defi お客 様相談室までお問い合わせください。

●検査を依頼される際には、製品の他に保証書とお客様情報を必ずご提示ください。

中古製品を購入しご使用される場合や、中古車を購入し取り付けられていた製品をご使用いただく場合は、必ず Defi で点検(有償)してからご使用ください。また、5年以上ご使用になった場合も Defi で点検(有償)してください。

取付後も製品本体、ハーネス、センサー部などを定期的に点検し、異常がない ことをご確認の上、十分注意してご使用ください。



**お客様情報** 検査を依頼する際には、お店の担当者に以下のことをおことづけください。

1. お客様のご連絡先					
郵便番号・住所:					
氏名:					
電話番号:					
メールアドレス:					
2. 購入店と取り付け作業先(連	極先)				
年式:					
型式:					
エンジン型式:					
排気量:					
ギアミッション (MT/AT):					
リミッターカット	有	無			
純正タコメーター	有	無			
エンジン載せ換え	有	無			
社外点火システムへの変更	有	無			
ECU 変更	有	無			
センサー取付方法:					
その他の仕様:					
4. お使いの Defi 製品					
(検査依頼する製品以外にも取り付けて	ている場合	はその製	温も)		
5. 動作の状況	» 1» > L	t. = t. =	7 - W - III	2)	
(いつ?何をしたら?どの製品が?何た	いどうなっ	たのか?	その後の状況は	?)	



#### **■**ラベルについて

製品に貼ってあるラベルは製品情報を特定するためのものです。 絶対に剥がさないでください。

#### ■廃棄方法について

製品を廃棄する際は、廃棄物処理法ならびにお住まいの自治体のルールに従って処理してください。パッケージについてはリサイクルが可能です。(パッケージに記載されているリサイクルマークをご覧ください。)



# Safety Warning [Please read carefully.]

This product is required for ADVANCE gauges and displays. This product does not function alone. Please use this product with ADVANCE gauges or displays. As for installation and operation, please refer to the manual for the gauges and displays as well.

This product is an additional product for providing information to automobile users about engine conditions and other important factors. When installing and operating this product, be sure to read the cautionary items of this operation manual as well as those given in the operation manual for the vehicle in which this product will be installed. Please obtain a full understanding of the cautionary items and use the product accordingly.

In the event that this product (or the vehicle in which it is installed) is lent to or transferred to another person, please be sure this operation manual and warranty card accompany the product.

In this manual, the degree of hazard arising from actions such as improper operation is separated into the 3 levels "Danger," "Warning," and "Caution." In addition, instructions that must be followed for safe and proper use of this product as well as practices that must be maintained are marked with a "Confirmation" heading. Please read and become familiar with these sections.

<b>⚠</b> Danger	Indicates a hazard that could cause death or serious per-
Zis Danger	sonal injury if the product is mishandled.
<b>↑</b> Warning	Indicates the possibility of death or serious injury if the prod-
Z!\ Warriing	uct is mishandled.
<b>⚠</b> Caution	Indicates a conceivable source of personal injury or damage
Zi Caution	to equipment if the product is improperly operated.
CC	Indicates an instruction that must be performed or practice
Confirmation	that must be maintained.

Properties for safety warning

'	, 3
$\triangle$	Indicates attention needs to be paid. (Including warnings)
○ Prohibited	Indicates restricted actions. (PROHIBITED actions)
Must	Indicates actions that need to be carried out. (MUST actions)



#### ■ Before handling (for installation personnel)

# ⚠ Danger

- Ensure that the vehicle will remain stationary and turn off the engine before installing this product. Failure to do so could result in a fire, and could make the vehicle move during installation.
- Remove the key from the ignition and disconnect the negative (-) battery terminal prior to installation of this product. Failure to do so could result in a fire caused by an electrical short circuit.
- ⚠ Take care not to install this product in a way that interferes with safety equipment such as seat belts and air bag systems or vehicle operation equipment such as engine controls, steering wheel and brake systems. Interference with normal operation of the vehicle can result in an accident or fire.
- Solder or use a solderless connector for wiring connections and make sure connections are insulated. In areas where there could be tension or sudden impacts on the wiring, safeguard the wiring with corrugated tubing or other shock absorbent material. Accidental shorts can cause fires
- While wiring power supply wire, to avoid the risk of electrical shock or fire, be sure to confirm that there is no disconnection or breakage of wire. Poor connection can result in short-circuit, electrical shock, fire, or other hazards.
- The ignition-switched +12V(IGN) line must be connected to the vehicle's ignition-switched wire with a fuse of 30A or less. High-capacity fuse(more than 30A) will not blowout even with an abnormal current flow and may cause fire.
- Discontinue use of this product if a blowout of the fuse has occurred. Continued use while the condition exists could result in an accident, fire, or damage to the vehicle.
- Use the tube fuse of regulated capacity when the fuse of the power wire is changed. Using a fuse that exceeds regulated capacity may cause fire.
- O Do not install the product in wet places. It may result in a fire caused by an electrical short circuit.
- Discontinue use of this product if the product doesn't operate or operates improperly. Continued use while the condition exists could result in an accident or damage.



# ⚠ Warning

- Carefully consider the installation location and driver's operation of the product before installation. Do not install the product where it interrupts driving and the safety deices of vehicle such as air bags. Be sure not to install the unit where it could fall. Improper installation or operation could cause the product to fall and damage the vehicle or cause serious danger by impeding driving.
- O Do not disassemble or modify this product. Such actions can not only damage or destroy the product but also will void the warranty.
  Disassemble/ Modify
- O Do not perform installation of this product immediately after the engine has been switched off. The engine and exhaust system are extremely hot at this time and can cause burns if touched.
- Ensure that the wiring of this product does not have an adverse impact on the other wiring of the vehicle. Incorrect wiring may destroy your ECU, ignition system and other engine management devices. When tapping engine rev or speed signal from the ECU, please make sure to follow the procedure as below:
  - 1. Make sure that you have connected the power supply wire of the advance control unit.
  - 2. Confirm that the DC Source LED of the advance control unit is lighted with ignition on.
  - 3. Remove negative terminal connector from battery and tap engine rev or speed signal from ECU.
- O Do not cut more than one wire at the same time when cutting wires. Cutting several wires together may destroy your ECU, ignition system and other engine management devices.
- Please keep children and infants away from the installation area. Children may swallow small parts or be injured in other ways.
- O Do not install this product in the area where safety equipment such as air bags are mounted. This may cause more injuries in the event of accident.



#### **⚠** Caution

• This product is designed for use on 12V vehicles. Do not install this product on vehicles with 24V systems.



- Insulate any unused wires. If any wires or connectors loosen during installation, please make sure they are correctly reattached.
- O Do not drop any of the components of this product. It may result in damage to the product.
- O Do not apply excessive force on switches/terminals. It may result in damage to the product.
- ♦ Do not use wires other than the provided wires.
- O Do not attach wires on the body of the vehicle or engine parts as this may result in damage to the product.
- ⚠ Install wires away from ignition and also radio signal frequency interference
  as this could cause the gauges to malfunction.
- ⚠ Please set it up so that the equipment such as the wireless machines and cellular phones that emit electric waves should not touch the unit. It may result in incorrect operation.
- O Do not place wires near the engine, exhaust pipe or turbine. It may result in damage or fusion of wires.
- $\triangle$  Make sure the waterproof processing is done when diverging wires in the engine compartment. Over 90°
- O Do not lay the gauge face down due to oil leakage. Angle "A" must be more than 90 degrees.
- ⚠ When installing the sensor, do not bend the wire near the sensor body.
- Wear gloves to avoid burns when soldering and cuts when installing wires, sharp edges of parts.
- O Do not expose the unit to moisture, dust or direct sunlight, or place product directly in front of heat vents.
- Install sensors away from hot or wet places.
- When using sunshade, put sunshade between products and windshield to avoid direct sun exposure.
- ⚠ Use a dried soft cloth for cleanup. Do not use cleaners except neutral detergent. It may damage the product.



O not pull the wires out of connectors forcefully. The connectors may be broken and the wires may be cut. When pulling out the wires, press the lock firmly to unclip the locks of connectors.



O not install gauges, including this product, into the passenger side or center of the dashboard. It doesn't meet vehicle safety standards.

#### Confirmation

- Be sure to follow all instructions in this manual to ensure safe installation and operation of the product.
- ⚠ When the negative (-) battery terminal is disconnected, equipment such
  as clocks and audio components having internal memory may lose their
  memory data. Follow the operation manual of each component to reset
  data after installation of this product.
- After installation is complete, return this operation manual, warranty card, and the package along with the warranty to the customer.
- $\triangle$  The gauge pointer may not be in the proper position when you purchase the product. Normal function will resume when power is connected.
- Please confirm with the maintenance book that the car manufacturer issued when installing and detaching genuine parts.
- Before tapping wires, check the voltage of the existing wire. After tapping the wire, check the voltage of the tapped wire again to confirm whether you have tapped into the proper place.
- ⚠ If car navigation system or car television is installed in vehicle, gauges and wires of this product need to be kept as far away as possible from the wiring and installing positions of car navigation system or car television. Failure to do so may result in interference of television display(VHF).
- ⚠ On no event will Nippon Seiki Co., Ltd. be liable to you for any damages or losses of genuine parts for your vehicle while installing.
- About Installation and Operation (for customer and installation personnel)

#### ♠ Warning

Please have this product installed by store professional or dealer where it was purchased. Installation by the customer will void the warranty.



© Do not disassemble or modify this product. Such actions will not only void the warranty but also damage or destroy the product.



- In order to ensure safe driving, check the information on the gauge only for a short period of time. Looking at the display for a long period of time could distract attention from the road and result in an accident.
- Discontinue use of this product if the gauge doesn't operate, water gets into the unit, or smoke or a strange odor comes from the unit. If such a condition occurs, contact the store or installation personnel as soon as possible. Continued use while the condition exists could result in an accident or fire.
- O Do not operate while driving.
- Fix the switch unit and other parts tightly to the vehicle to avoid children's accidentally swallowing them.
- O Do not use the TIME ATTACK function of ADVANCE ZD in open roads. It is only for closed courses.

# **⚠** Caution

- ⚠ On no event will Nippon Seiki Co., Ltd. be liable for any damages arising out of the use or inability to use the product, even if Nippon Seiki Co., Ltd. has been advised of the possibility of such damage.
- O Do not pull the wires out of connectors forcefully. The connectors may be broken and the wires may be cut. When pulling out the wires, press the lock firmly to unclip the locks of connectors.

#### Confirmation

- ⚠ This product cannot be linked to the previous version of Defi-Link System.
- The information displayed on this product are for reference purposes only. Please drive according to the indication of vehicle's originally equipped instruments.
- O Do not connect more than one gauge of the same variety. (Ex. You can NOT connect 2 turbo gauges together.)
- $\triangle$  This product can be used only on 1, 2, 3, 4, 5, 6, and 8 cylinder vehicles with 4 cycle engine. This product cannot be used on diesel vehicles.
- ⚠ In the case of idling stop vehicles, the power of the product is turned off and restarted in some cases by a drop in battery voltage when the engine is



restarted while idling stop function is active. It is not malfunction.

- Please check the installed product regularly. Durability might deteriorate according to use conditions, etc.
- Dispose of the product according to the local recycling regulations.

# Product Features

- Interactive communication advanced system is implemented.
- Up to 7 ADVANCE gauges and displays in all can be controlled.
- Gauges can be controlled from distance with the included switch unit. The illumination color is white.
- By connecting ADVANCE ZD to the ADVANCE system, the illumination of ADVANCE gauges is controlled automatically.
- Opening and ending modes can be selected from 2 variations.
- The installation of additional gauges is easy. Just connect it to other gauge and attach the sensor to ADVANCE Control Unit.
- Self-diagnosis system turns on the warning display to indicate any wire disconnection, short circuit and serial communication errors.
- Warning by buzzer sound when the warning display is on (buzzer sound can be turned on / off).
- Peak value and warning value during driving are stored. Driving data can be stored and replayed up to 3 minutes.
- Mounting kits are provided with gauges and displays.
- With both fuel pressure and turbo sensors installed, differential pressure can be monitored on the fuel pressure gauge or ADVANCE ZD.



# **3** List of Products

Product name	Product No.
Defi-Link ADVANCE Control Unit	DF07703

Product Name	Product No.	
Defi-Link Meter ADVANCE ZD	DF09701	

# ■ ADVANCE CR/RS gauges Φ 52 series (SI models)

Product name	Display range	CR White Dial	CR Black Dial	RS Black Dial
Turbo2.0	-100kPa ∼ +200kPa	DF07801	DF07802	DF13501
In-Mani Press (※1)	-100kPa ∼ +20kPa			DF13601
Oil Press	0 ∼ 1000kPa	DF08101	DF08102	DF13701
Fuel Press	0 ∼ 600kPa			DF13801
Oil Temp	50 ∼ 150℃	DF08301	DF08302	DF13901
Water Temp	20 ∼ 120℃	DF08401	DF08402	DF14001
Exhaust Temp	200 ∼ 1100°C			DF14101

# ■ ADVANCE CR gauges Φ 60 series (SI models)

Product name	Display range	White Dial	Black Dial
Turbo2.0	-100kPa ∼ +200kPa	DF08601	DF08602
Turbo1.2	-100kPa ∼ +120kPa	DF08701	DF08702
In-Mani Press (%1)	-100kPa ∼ +20kPa	DF08801	DF08802
Oil Press	0 ∼ 1000kPa	DF08901	DF08902
Fuel Press	0 ∼ 600kPa	DF09001	DF09002
Oil Temp	50 ∼ 150℃	DF09101	DF09102
Water Temp	20 ~ 120℃	DF09201	DF09202
Exhaust Temp	200 ∼ 1100°C	DF09301	DF09302
Tachometer	0 ∼ 9000rpm	DF09403	DF09404



# ■ ADVANCE BF/A1 gauges Φ 60 series (SI models)

Product name	Display range	BF White Model	BF Amber Red Model	BF Blue Model	A1
Turbo3.0	-100kPa ∼ +300kPa	DF14701	DF14702	DF14703	DF14901
Turbo2.0	-100kPa ∼ +200kPa	DF09901	DF09902	DF09903	DF14801、02( ※ 2)
Turbo1.2	-100kPa ∼ +120kPa	DF10001	DF10002	DF10003	
In-Mani Press (%1)	-100kPa ∼ +20kPa	DF10101	DF10102	DF10103	
Oil Press	0 ∼ 1000kPa	DF10201	DF10202	DF10203	DF15001
Fuel Press	0 ∼ 600kPa	DF10301	DF10302	DF10303	DF15101
Oil Temp	50 ∼ 150℃	DF10401	DF10402	DF10403	DF15201
Water Temp	20 ∼ 120℃	DF10501	DF10502	DF10503	DF15301、02( ※ 2)
Exhaust Temp	200 ∼ 1100℃	DF10601	DF10602	DF10603	DF15401
Tachometer	0 ∼ 9000rpm	DF10704	DF10705	DF10706	

# ■ ADVANCE BF gauges Ф 2 3/8" series (USDM models)

Product name	Display range	BF Amber Red Model
Boost	-30inHg ∼ +29PSI	DF09904
Oil Press	0 ∼ 145PSI	DF10204
Fuel Press	0 ∼ 87PSI	DF10304
Oil Temp	122 ∼ 302°F	DF10404
Water Temp	68 ∼ 248°F	DF10504
Exhaust Temp	392 ∼ 2010°F	DF10604

# ■ ADVANCE gauges Ф 80 series

Product name	Display range	BF White Model	BF Amber Red Model	BF Blue Model	RS	A1
Tachometer	0 ∼ 9000rpm	DF10901	DF10902	DF10903	DF14201	
Tachometer	0 ∼ 11000rpm	DF11001	DF11002	DF11003	DF14301	DF15501



- ⚠ This product is a required for ADVANCE gauges and displays. This product alone does not operate. Please use this product with gauges or displays listed above. As for installation and operation, please refer to the manual for gauges and displays as well.
- \* 1: In-Mani Press is an abbreviation of Intake Manifold Pressure.
- \*\* 2: Sensors, sensor wires, and sensor installation parts are not included in DF14802 and DF15302.

#### 4 Specification

- Power supply voltage  $10V \sim 16V$  DC(For 12V vehicle)
- Current Consumption
- Maximum value in case 7 gauges or displays are connected

+B line 2A(IGN ON)/5mA(IGN OFF)

ILM line 800mA

■ Illumination color Control Unit DC Source LED: blue.

Switch unit: white (while illumination is on)

Switch unit D mark for differential pressure: blue

- Applicable number of cylinders 1.2.3.4.5.6.8 (4cycle)
- Temperature range(Under 80% relative humidity) Unit: °C (°F)

	Storage	Operational
CR/RS/BF/A1/ZD	-30 (-22) ~+80 (176)	-20 (-4) ~ +60 (140)
ADVANCE Control Unit	-30 (-22) ~+80 (176)	-20 (-4) ~ +60 (140)
Switch Unit	-30 (-22) ~+80 (176)	-20 (-4) ~ +60 (140)
Boost sensor	-30 (-22) ~+100 (212)	-30 (-22) ~ +80 (176)
Press. sensor	-30 (-22) ~+140 (284)	-30 (-22) ~ +120 (248)
Temp. sensor	-30 (-22) ~+150 (302)	-20 (-4) ~ +150 (302)
Exhaust Temp. sensor	-30 (-22) ~+130 (266)	-30 (-22) ~ +130 (266)


- % The upper temperature limit of sensor connectors is 105°C (221°F).
- \*\* The sensing part of exhaust temp. sensor is not included in the temperature range above.



Clip 1pc

### 5 Parts List/Part Names/Dimensions

# 5 -1. Parts List




 $\triangle$  Operation manual (this booklet) and warranty card are included with the parts listed above.

Nut 4pcs

Bolt 4pcs



## 5 -2. Part Names & Dimensions of Control Unit in mm(inches)




- Connectors for wires
- Switch unit(white)
- ② Speed&Tachometer signal wire(blue)
- ③ Exhaust temp sensor wire(black)
- 4 Water temp sensor wire(pink)
- (5) Oil temp sensor wire(red)
- 6 Fuel press sensor wire(red)
- Fuel press sensor wire(rea)
- ⑦ Oil press sensor wire(white)
- ® Turbo/In-Mani sensor wire(light blue)
- Power source wire(beige)
- 10 Meter wire(white) 11 Meter wire(white)
- ⚠ Meter wires can be connected to both ⑩ and ⑪ . To protect against short-circuit between two terminals, the convex connector is inserted into the concave connector ⑪ at the factory prior to shipment. If You don't use ⑪ , do not remove the convex connector. When using ⑪ , please pull out the convex connector by pressing the lock, and then connect the meter wire.


- Dip switch 1&2
- 1: Warning buzzer sounds ON/OFF change
- 2: Opening Closing modes selection(A/B)



#### 5 -3. Part Names & Dimensions of Switch unit in mm(inches)



Backside of switch unit



Buttons and slide switch

Operation of gauges is handled by 3 buttons and 1 slide switch. By sliding the switch position, the functions of buttons change.

#### Slide switch

In this manual, positions of the slide switch are illustrated as follows:

REAL(upper): for Real mode operation

UREAL

PLAY(middle): for operation to replay recorded data

M PLAY

SET(lower): for operation to set up

L SET

#### Buttons

Each button has three marks(upper, middle, and lower position) in accordance with positions of slide switch. In this manual, each button is illustrated as follows:

Left Right Right

Left button: ■●REC or ■►PLAY or ■!WARN.SET from the top
Middle button: ■●PEAK or ■ or ■ from the top
Right button: ■DIM/RESET or ■ or ■ from the top




#### 6 Installation

#### Confirmation

Please refer to how to install gauges, displays, and sensors of each manual as well as this manual.

#### 6 -1. Installation diagram



The meter wire can be connected to both two connectors of METER OUTPUT. Up to 7 gauges and displays in all can be connected to one control unit. (Ex. If 7 gauges are connected to one line, none can be connected to the other line. If three gauges are connected to one line, up to 4 gauges can be connected to the other line.)

O Do not connect more than one gauge of the same variety. (Ex. You can NOT connect 2 turbo gauges together.) However, several ZDs can be connected.



#### 6 -2. Procedure

- 1. Confirm the contents.
  - $\Rightarrow$  Please refer to operation manuals included with components and each gauge.
- 2. Confirm and prepare the necessary parts for installation.
  - ⇒ Refer to the operation manual included with each gauge.
  - Please purchase commercially available attachment parts.
- Confirm the location of the power source(Battery, GND, IGN, ILM) and the sensor installation.
- 4. Disconnect the negative(-) battery terminal.
- 5. Connect the power supply wire to vehicle.
  - $\Rightarrow$  Refer to  $\stackrel{f 6}{ ext{ }}$  -3. How to solder  $\cdot$  How to use the solderless connectors.



## /\ Warning

- O Do not connect the IGN wire to the ACC (power source for accessory) wire. Failure to do so way lead to a malfunction or accident.
- 6. Connect the power supply wire to the control unit. Connect the negative battery terminal and turn the ignition on. Then confirm DC SOURCE LED lights up, which is on the front of the control unit.

#### Confirmation

- $\triangle$  If the power source wire is wired incorrectly, LED won't light. If LED doesn't light, please confirm wiring again.
- Disconnect the negative battery terminal and install each sensor.
   ⇒ Refer to the operation manual included with each gauge.
- 8. Connect the sensor and the sensor wire. Then connect to the control unit.




- To confirm the wiring and connection, connect gauges and displays to the control unit temporarily by using meter wires. Do not fix the gauge at this stage.
- O Do not remove the convex connector if you use only one METER OUTPUT connector to protect against short-circuit between two terminals.
- 10. Connect the negative battery terminal.
- 11. Confirm that the DC SOURCE LED is on when the ignition is on. If the power supply wire is wired correctly, the DC SOURCE LED of the control unit lights in blue. And also look see that CR gauges' illumination lights up/BF gauges' illumination darkens/ZD's switch illumination lights up when the illumination switch of the vehicle is on
- The DC SOURCE LED is not on: The power supply is not taken.
- → Turn the ignition off, then please confirm the wiring of the power supply wire.
- The warning LED of gauge is blinking or the warning LED and peak LED are blinking at the same time: disconnection, short circuit, or communication error is occurred
  - $\Rightarrow$  Refer to  $\ensuremath{\,\overline{\!\!\mathcal{O}}}$  -3-2. Error displays of wire disconnection, short circuit, and serial error.
- → Turn the ignition off, then please confirm the wiring of the sensor and the sensor wire.

# **⚠** Warning

- If the wiring defects are not found, it is probable that there is a defect in the product. Please detach the product immediately and ask for inspection. It may damage the vehicle.
  - ⇒ Refer to 10 Maintenance & Check & Servicing.
- 12. Turn the ignition OFF.



- 13. Disconnect the meter wire from the gauge, and attach the gauge by using mounting bracket. Confirm it is installed firmly, then connect the meter wire again.
  - ⇒ Refer to each gauge operation manual
- 14. Connect the switch unit to the control unit and fix the switch unit with double sided tape. Before attaching it, make sure the surface is clean.
  - ⇒ Refer to ⑤ -3. Part Names & Dimensions of Switch unit in mm(inches).
- 15. Set 2 dip switches of the control unit.
- Dip switch 1: Setting the buzzer sound ON/OFF.
- Dip switch 2: Select the opening/ending mode from A or B when the ignition is on/off.
  - ⇒ Refer to ⑤ -2. Part Names of Control Unit in mm(inches), ⑦ -6-2. Set the warning buzzer ON/OFF, and ⑦ -2-1. Change of Opening mode / Ending mode.
- 16. After setting is done, fix the control unit with attached nuts and bolts and commercial mounting bracket.



#### Confirmation

Q Gauges, including this product, are not waterproof. Please do not install gauges near the vehicle floor or in wet areas.



- Use mounting brackets with thickness of 3mm(0.1") and under.
- O Do not use other than the supplied bolts. Use of other bolts may damage the inside of the control unit.
- ⚠ The control unit contains buzzer. So it may difficult to hear the sounds if the control unit is installed inside the dashboard or far from driver's seat.
- It is possible to change the setting later. In order to change later, please fix the control unit so as to operate the dip switch.
- 17. Final confirmation of install completion

there is no liquid or exhaust leakage.

# **⚠** Warning

Please be sure to check the following list; otherwise, there is a possibility that a serious accident may occur.

☐ Ensure that all hoses and tubing are permanently attached. Also ensure that

$\hfill \Box$ Check that the sensor and wires are not interfering with the engine operation.
☐ Ensure that the gauge and wires are tightly attached, so they don't come loose and hinder driving.
$\hfill\Box$ Check that all wires disconnected from the vehicle during installation have

# **⚠** Warning

been properly reattached.

• After installation, check that no materials or tools remain in the driver's seat or the engine compartment. If there are tools left at the feet of the driver's seat, this may cause a driver to lose control of brake because of tools or materials caught under the brake pedal. If there are tools in the engine compartment, the engine may break.



 $\hfill \Box$  Ensure that the negative battery terminal is tightly attached. Close the hood properly.

This concludes the installation process.

#### Confirmation

The protection film is attached to ADVANCE Control Unit and the switch unit. Please peel off before using. It may be sticked by aging of the glue.



#### 6 -3. How to solder • How to use the solderless connectors

## 

- Wear protective gloves to avoid getting burned during soldering.
- Soldering is a better choice for wiring. Make sure no loose connection is found
- How to solder





(Apply an appropriate amount of solder)




(2) Wind to fasten the peeled wire



(4) Wrap tightly with insulating tape



How to use the solderless connectors





Make sure both left hook and right hook are locked firmly.

\*Use of needle nose plier may lead to poor contact. Use plier.

## Confirmation

- The solderless connectors that come with the product are for cable core of 0.3mm  $\sim 0.75$ mm diameter. Use them within the range.
- O Do not use the solderless connectors on wires that have thicker cable core than 0.75mm diameter. Cable core might be broken and produce heat.



# **7** Operation

In this instruction, there are two kinds of ways to press buttons, "press" and "press long." For "press," press the button for less than 1 second. For "press long," press the button for more than 1 second.

# 7 -1. Setting and checking of operations

- 1. Turn the ignition on and confirm the DC Source LED on the control unit is lighted up.
  - ⇒ Refer to 6 Installation.
- 2. Confirm that the opening mode is performed.
  - $\Rightarrow$  Refer to  $\boxed{2}$  -2. Opening mode / Ending mode.
- Confirm that there is no error message of wire disconnection/short circuit on the gauges and ZDs.
  - $\Rightarrow$  Refer to  $\overline{\textit{1}}$  -3-2. Error displays of wire disconnection, short circuit, and serial error.
  - If an error is displayed
    - → Turn the ignition off immediately, and then confirm the wiring of the sensor and the sensor wire.
- 4. If the tachometer is installed, please set the number of cylinders and the response.
- ⚠ If ZDs are installed as well, settings for tachometer need to be done in System Setup Mode of ZD. The settings of ZD are applied to other tachometers connected to the ADVANCE System. Refer to ZD manual for setting. If you don not install either ZD or tachometer, go to next step.
  - ⇒ Refer to ⑦ -4. Setting number of cylinders mode and ⑦ -5. Setting Tachometer response mode.
- 5. Set warning values for all the connected gauges and ZDs. And then select illumination color for CR/RS gauges. Warning values for gauges and ZDs are set at the same time.
  - $\Rightarrow$  Refer to  $\bigcirc$  -6-3. Change the illumination color.
- Confirm gauges and ZDs function normally. Setting is finished by confirming the operations.

# **⚠** Warning

• Please set while the vehicle is stopped.



#### **7** -2. Opening mode / Ending mode

When the ignition is turned on, gauges and ZDs perform opening mode. When the ignition is turned off, gauge and ZDs perform ending mode and then the power supplies of the control unit, gauges, and ZDs are shut off.

#### Confirmation

- ⚠ Depending on vehicles, the ignition is not turned off immediately after the key is turned off. In this case, ending mode doesn't start until the ignition is turned off.
- $\underline{\wedge}$  If the ignition is turned off during setting, the setting data will not be saved.
- If the power wire is wired correctly, the DC Source LED lights in blue from the beginning of opening mode. If it stays off or is blinking, turn the ignition off and check the wiring.
  - ⇒ Refer to 6 Installation.

#### 7 -2-1. Change of Opening mode / Ending mode

Opening and ending modes can be selected from A type (simple) and B type (special) by sliding the dip switch 2 on the control unit.

Both types consists of lighting/blinking of peak & warning LED, the dial illumination, and sequential indicators of ZD, besides pointer movement and digital display on ZD. Try both types!

- Please slide the switch when the ignition is off. The modes for all the connected gauges and ZDs are changed at the same time.
- $\triangle$  It might be hard to see the dial illumination depending on outside light level.

#### 7 -3. Real Mode (slide switch position: UREAL)

After the opening mode finishes, the gauge shifts to Real mode. The real-time vehicle conditions are displayed during Real mode.




#### 7 -3-1. Warning display

If the gauge reaches or exceeds the value set for warning, the warning LED goes on. In case of oil pressure and fuel pressure, when the gauge reaches or falls below the value set for warning, the warning LED goes on. The zone that the warning item is displayed is highlighted on ZD display. If the buzzer sound setting is on, the buzzer sounds at the same time as well.

# **7** -3-2. Error displays of wire disconnection, short circuit, and serial error If there are disconnection of wire and/or sensor, or short circuits of wire and/

or sensor, the warning LED blinks. Error messages are displayed on ZD display. Once the error message is displayed, the warning LED keeps blinking until the ignition is turned off. Please turn off the ignition immediately and check the wiring of sensors and wires. The short-circuit error displays for oil pressure and fuel pressure are displayed only during short-circuiting.

If the communication between gauges/ZDs and the control unit is failed, serial error massage is displayed and warning and Peak LEDs blink at the same time.



If an error is displayed, turn the ignition off immediately, and then confirm the wiring of the sensor and the sensor wire. If any defects are not found, please ask the shop for inspection.

#### 7 -3-3. Illumination

[ADVANCE CR/RS gauges]

The illumination of CR/RS gauges are turned on/off being interlocked with the vehicle illumination switch.



By pressing (RIDIM/RESET) button several times during Real mode, Record mode or Playback mode, the gauge illumination is turned off even if the vehicle illumination is on. (Illumination cancel)

#### [ADVANCE BF/A1 gauges]

The brightness of gauge illumination can be adjusted by pressing DIM/RESET button during Real mode, Record mode, or Playback mode. Five levels of brightness are provided for daytime and nighttime separately. The brightness level is shifted from daytime level to nighttime level being interlocked with the vehicle illumination switch.

By pressing (RIDIM/RESET) button several times during Real mode, Record mode or Playback mode, the gauge illumination is shifted to the maximum brightness level even if the vehicle illumination is on. (Illumination cancel)

#### [ADVANCE ZD]


A dimming sensor is equipped with ZD. For brightness adjustment, either AUTO or MANUAL control can be selected. If AUTO is selected, the brightness of ZD display is adjusted automatically depending on the outside light. By connecting ZDs to the control unit and using AUTO control, the illuminations of the switch unit and connected gauges of ADVANCE series are controlled automatically.

Switch unit/ADVANCE CR/ADVANCE RS: Turned ON/OFF automatically ADVANCE BF/ADVANCE A1: Adjusted automatically

#### 7 -3-4. Differential Pressure Display

If both of the turbo and the fuel pressure gauge are installed (both of the turbo and fuel pressure sensors are installed in case of ZD), the fuel pressure gauge can indicate the differential pressure value between fuel pressure and intake manifold pressure. During Real mode, the indicator of DIFFERENTIAL PRESSURE on the switch unit is lighted up in blue. The differential pressure can be displayed in Record Mode as well.





About differential pressure display of fuel pressure; Generally, fuel pressure of electric controlled engine car is controlled to keep in same ratio to intake manifold pressure by fuel pressure regulator. As shown in the graph, fuel pressure meter displaying absolute pressure value indicates 400kPa when boost pressure is 100kPa in case that differential pressure is set at 300kPa. Fuel pressure meter displaying the differential pressure ressure walue indicates 300kPa.

- 1. Set the slide switch to **UREAL**.
- 2. If the MOPEAK button and RDIM/RESET button are pressed at the same time, the fuel pressure gauge displays the differential pressure and the indicator of DIFFERENTIAL PRESSURE on the switch unit is lighted up. To cancel, press MOPEAK button and RDIM/RESET button together again.
- 7 -4. Setting number of cylinders mode (slide switch position: **SET**) When the tachometer is installed, please set the number of cylinders. factory default setting: 4 cylinder
- ⚠ If ZDs are installed as well, settings for tachometer need to be done in System Setup Mode of ZD. The settings of ZD are applied to other tachometers connected to the ADVANCE System. Refer to ZD manual for setting.
- 1.Set the slide switch to **L SET**
- 2.When the LIWARN.SET button is pressed long, the gauge shifts to Setting number of cylinders mode, and warning and peak LEDs on the gauge blink alternately.

If ZDs are installed, the system moves into System Setup Mode of ZD not tachometer setting mode. LEDs on the gauge doesn't blink. When the tachometer is not installed, the system does not shift to Setting number of cylinders mode.



- 3. When the  $\bigcirc$  button is pressed, the number of cylinders changes into  $1 \rightarrow 2 \rightarrow 3 \rightarrow 4 \rightarrow 5 \rightarrow 6 \rightarrow 8$ . When the  $\bigcirc$  button is pressed, the number of cylinders changes into  $1 \rightarrow 2 \rightarrow 3 \rightarrow 4 \rightarrow 5 \rightarrow 6 \rightarrow 8$ . When the  $\bigcirc$  button is pressed, the number of cylinders changes into  $1 \rightarrow 2 \rightarrow 4 \rightarrow 3 \rightarrow 2 \rightarrow 1$ . For example, when the number of cylinders  $1 \rightarrow 3 \rightarrow 4 \rightarrow 3 \rightarrow 2 \rightarrow 1$ . For example, when the number of cylinders  $1 \rightarrow 4 \rightarrow 3 \rightarrow 2 \rightarrow 1$ . For example, when the number of cylinders  $1 \rightarrow 4 \rightarrow 3 \rightarrow 2 \rightarrow 1$ . For example, when the number of cylinders  $1 \rightarrow 4 \rightarrow 3 \rightarrow 2 \rightarrow 1$ . For example, when the number of cylinders  $1 \rightarrow 4 \rightarrow 3 \rightarrow 2 \rightarrow 1$ . For example, when the number of cylinders  $1 \rightarrow 4 \rightarrow 3 \rightarrow 2 \rightarrow 1$ .
- 4. After completion of setting, return the slide switch to **UREAL** or **MPLAY**.

# 7 -5. Setting Tachometer response mode (slide switch position: LSET)

If tachometer has been installed, the response needs to be set. There are 3 levels.

Factory default setting: Position 1

⚠ If ZDs are installed as well, settings for tachometer need to be done in System Setup Mode of ZD. The settings of ZD are applied to other tachometers connected to the ADVANCE System. Refer to ZD manual for setting.

By checking needle pointer movement, adjust the response speed.

Position 1	faster	1000rpm	
Position 2	middle	2000rpm	
Position 3	slower	3000rpm	

- 1. Set the slide switch to **L SET**.
- If the LIWARN.SET) button is pressed long, the gauge shifts to Setting the number of cylinders mode. The peak and warning LEDs on tachometer blink alternately.
  - If ZDs are installed, the system moves into System Setup Mode of ZD not tachometer setting mode. LEDs on the gauge doesn't blink. If the tachometer is not installed, the system does not shift to Setting numbers of cylinders mode or Setting Tachometer response mode.
- 3. If the **!!WARN.SET**) button is pressed long during Setting the number of cylinders mode, the gauge shifts to Setting Tachometer response mode.



The peak and warning LEDs in the gauge are lighted up.

- 4. If the  $\bigcirc$  button is pressed, the position changes into  $1 \rightarrow 2 \rightarrow 3$ . If the  $\bigcirc$  button is pressed, the position changes into  $3 \rightarrow 2 \rightarrow 1$ . 1000rpm, 2000rpm and 3000rpm indicate Position 1, Position2 and position3 respectively.
- 5. Return the slide switch to **UREAL** or **MPLAY**.

# 7 -6. Setup mode (slide switch position : LSET)

By setting warning values, the warning LEDs on the gauges light on when the gauges reach or exceed the values. In case of oil pressure and fuel pressure, when the gauge reaches or falls below the value set for warning, the warning LED lights on. If ZDs are installed, warning setting is displayed on ZD display. Warning values for gauges and ZDs are set at the same time.

In addition, the illumination color of CR/RS gauges can be selected from 2 colors in this mode. Illumination color of BF/A1 and ZD can not be changed.

#### ■ Warning factory default settings

		Setting range			
Gauge	default setting	Unit	Minimum	Maximum	Lighting condition
Turbo3.0	166.7	kPa	-100	300	set value and above
Turbo1.2/2.0	100	kPa	-100	200	set value and above
In-Mani Press	10	kPa	-100	300	set value and above
Tachometer	7000	rpm	300	11000	set value and above
Oil Press	120	kPa	0	1000	set value and below
Fuel Press	150	kPa	0	600	set value and below
Oil Temp	125	$^{\circ}$	0	150	set value and above
Water Temp	105	$^{\circ}$	0	150	set value and above
Exhaust Temp	850	$^{\circ}$	0	1100	set value and above

• Depending on vehicle type and/or condition, vehicle may be damaged even if the value is under the warning factory default setting value (over the warning factory default setting value in case of oil pressure and fuel pressure). Be sure to consult store professional to set warning values.



#### **7** -6-1. Set the warning value

- 1. Set the slide switch to LSET
- 2. If the L! WARN. SET button is pressed, the gauge shifts to Setup mode.
- 3. Select the gauge by pressing **L!WARN.SET** button.

	Selected	Not selected	
CR/RS gauges	Warning LED: blinking	Warning LED: unlighted	
	Illumination: bright	Illumination: dark	
	(while vehicle illumination is ON)	(while vehicle illumination is ON)	
BF/A1	Warning LED: blinking	Warning LED: unlighted	
gauges	Illumination: bright	Illumination: dark	
ZD	Highlighted	Not highlighted	

⚠ In case that CR/RS gauges and ZDs are installed together and the dimmer setting is AUTO, the illumination of CR/RS gauges turned ON/OFF automatically regardless ON/OFF of the illumination switch of vehicle. If the setting is done in bright light, the illumination of CR/RS gauges may be unlighted. Please place a hand over the dim sensor of ZD or move vehicle to a dark place.

The only selected gauges will be displayed in the following order.

Turbo • In-Mani Press→Tachometer→Oil Press
↑ ↓

Exhaust temp←Water Temp←Oil Temp←Fuel Press

4. When the button is pressed, the warning value becomes lower, and when the button is pressed, the warning value becomes higher for the selected gauge. If each button is pressed long, the setting value changes quickly.

If turbo(2.0 or 1.2) and intake manifold gauge are installed together, the setting value of turbo(2.0 or 1.2) becomes the setting value of intake manifold. You cannot set the value separately for each gauge. When both turbo2.0 and turbo1.2 are connected, turbo2.0 has a priority over turbo1.2.

 $\bigcirc$  Do not connect more than one gauge of the same variety.



(Ex. You can NOT connect 2 turbo 2.0 gauges together.)

5. Return the slide switch to **UREAL** or **MPLAY**.

#### 7 -6-2. Set the warning buzzer ON/OFF

By sliding the dip switch1 of the control unit, the warning buzzer sound is turned ON/OFF. The switch operation sound cannot be canceled.

- Please set while the ignition is off.
- ⚠ The setting of warning buzzer for ZD is controlled by ZD. Refer to ZD manual.

#### 7 -6-3. Change the illumination color

Illumination color for CR/RS gauges can be selected from 2 colors. Illumination color of BF/A1 and ZD can not be changed.

- 1. Set the slide switch to **LSET**.
- 2. If the **! WARN.SET** button is pressed, the gauge shifts to Setup mode.
- 3. Select the gauge by pressing **L!WARN,SET** button.
- 4. When the **b**utton and the **b**utton are pressed at the same time, the illumination color changes.

CR white dial: blue ⇔ amber red

CR black dial: white ⇔ amber red

RS black dial: classic green ⇔ classic white

- ⚠ In case that CR/RS gauges and ZDs are installed together and the dimmer setting is AUTO, the illumination of CR/RS gauges turned ON/OFF automatically regardless ON/OFF of the illumination switch of vehicle. If the setting is done in bright light, the illumination of CR/RS gauges may be unlighted. Please place a hand over the dim sensor of ZD or move vehicle to a dark place.
- 5. Return the slide switch to **UREAL** or **MPLAY**.

# **7** -6-4. Offset adjustment of Turbo (2.0 and 1.2) and In-Mani Press

The needle pointer of turbo should indicate 0kPa when the ignition is on. But



in rare cases the needle pointer is not indicating exactly 0kPa. If this happens, it is possible to offset and adjust the needle pointer.

- 1. Set the slide switch to **LSET**.
- 2. If the **L!WARN.SET** button is pressed, the gauge shifts to Setup mode.
- 3. Select the gauge by pressing **! WARN, SET** button.
- Press long LIWARN.SET to adjust the gauge. The adjustment is confirmed by a short beep sound.
- 5. Return the slide switch to **UREAL** or **MPLAY**.

## 7 -7. Real Peak mode (slide switch position: UREAL)

The peak values recorded while driving and idling are displayed during Real mode. The maximum and minimum values are displayed in order as for oil pressure and fuel pressure. The peak values can be reset. The peak value of fuel pressure is displayed in the fuel pressure zone even while displaying the differential pressure.

IF NEITHER OIL PRESSURE NOR FUEL PRESSURE SENSOR IS CONNECTED:

- 1. Set the slide switch to **UREAL**.
- If the MOPEAK button is pressed, the gauge shifts to Real Peak mode. The LED is lighted up during Real Peak mode.
- 3. If the MOPEAK button is pressed, the gauge shifts to Real mode.

IF EITHER OIL PRESSURE OR FUEL PRESSURE SENSOR IS CONNECTED:

- 1. Set the slide switch to **UREAL**.
- If the MOPEAK button is pressed, the gauge shifts to Real Peak mode (maximum value). All the connected gauges display maximum values. The LED is lighted up during Real Peak mode.
- 3. If the MOPEAK button is pressed again, the gauge shifts to Real Peak mode (minimum value). All the connected gauges except oil pressure and fuel pressure display maximum values. The LED is lighted up during Real Peak mode
- 4. If the MOPEAK button is pressed, the gauge shifts to Real mode.



#### 7 -8. Real Peak Reset mode (slide switch position: UREAL)

The peak value of driving and idling data can be reset. Regarding oil pressure and fuel pressure, both the maximum value and the minimum value are reset.

- 1. Set the slide switch to **UREAL**
- If the MOPEAK button is pressed, the gauge shifts to Real Peak mode. The LED is lighted up during Real Peak mode.
- If the RDIM/RESET button is pressed during Real Peak mode, the LED starts blinking and the peak value is reset. After a reset, the gauge returns to Real mode.

# 7 -9. Record mode (slide switch position: UREAL)

Driving data can be recorded up to 3 minutes.

- 1. Set the slide switch to **UREAL**.
- 2. If the **Tec** button is pressed, the gauge shifts to Record mode and start recording. The LED is blinking during Rec mode.
- 3. If the **QOREC** button is pressed, the gauge finishes recording and returns to Real mode. Also after 3 minutes have passed from recording, the gauge returns to Real mode.

It is possible to turn off the illumination of gauges and to display the differential pressure during Rec mode.

 $\Rightarrow$  Refer to  $\bigcirc$  -3-3. Illumination and  $\bigcirc$  -3-4. Differential Pressure Display.

#### 7 -10. Rec Peak mode (slide switch position: **UREAL**)

The peak values recorded while recording are displayed during Record mode. The maximum and minimum values are displayed in order as for oil pressure and fuel pressure. The peak value of fuel pressure is displayed even while displaying the differential pressure.



#### IF NEITHER OIL PRESSURE NOR FUEL PRESSURE SENSOR IS CONNECTED:

- 1. If the MOPEAK) button is pressed during Rec mode, the gauge shifts to Rec Peak mode. The LED is lighted up during Rec Peak mode.
- 2. If the MOPEAK button is pressed again, the gauge returns to Rec mode. And then if the LOREC button is pressed, the gauge returns to Real mode. Or after 3 minutes have passed from recording, the mode returns to Real mode.

#### IF EITHER OIL PRESSURE OR FUEL PRESSURE SENSOR IS CONNECTED:

- If the MoPEAK button is pressed during Rec mode, the gauge shifts to Rec Peak mode (maximum value). All the connected gauges display maximum values. The LED is lighted up during Rec Peak mode.
- 2. If the MOPEAK button is pressed again, the gauge shifts to Rec Peak mode (minimum value). All the connected gauges except oil pressure and fuel pressure display maximum values. The LED is lighted up during Rec Peak mode
- 3. If the MOPEAK button is pressed again, the gauge returns to Rec mode.

  And then if the OREC button is pressed, the gauge returns to Real mode. Or after 3 minutes have passed from recording, the mode returns to Real mode

### 7 -11. Playback mode (slide switch position: MPLAY)

Recorded data can be replayed. Pausing, fast-forwarding, rewinding, single frame forwarding, and single frame rewinding are possible.

- 1. Set the slide switch to MPLAY.
- If the PLAY button is pressed, the gauge shifts to Playback mode and play the recorded data. The LED is blinking during Playback mode.
- When playback finishes or the button is pressed during playback, the gauge returns to Real mode.

The illumination of gauges can be turned off during Playback mode.

 $\Rightarrow$  Refer to  $\boxed{7}$  -3-3. Illumination.



### 7 -11-1. Operation during playback

- Playback is paused if the M S button or the R DD button is pressed during playback.
- If the R DD button is pressed during pause, playback goes frame by frame. If the R DD button is pressed long during pause, it fast forwards playback.
- If the M d button is pressed during pause, playback is rewound frame by frame. If the M d button is pressed long during pause, playback is rewound.
- If the **LPPLAY** button is pressed during pause, playback restarts.

playback ⇔ pause ⇔ single frame forward/rewind, fast forward/rewind

### 7 -12. Play Peak mode (slide switch position: MPLAY)

The peak values recorded while recording are displayed during Playback mode. The maximum and minimum values are displayed in order as for oil pressure and fuel pressure.

#### IF NEITHER OIL PRESSURE NOR FUEL PRESSURE SENSOR IS CONNECTED:

- 1. Set the slide switch to MPLAY.
- If the PLAY button is pressed, the gauge shifts to Playback mode and replays the data. The LED is blinking during Playback mode.
- 3. Set the slide switch to **UREAL** during playback (or pause).
- If the MOPEAK button is pressed during playback (or pause), the gauge displays the peak value of recorded data.
- 5. If the MOPEAK button is pressed again, the gauge returns to playback of the data. To return to Real mode, set the slide switch to MOPEAY and press long the LOPEAY button.

Data playback is ongoing during Play Peak mode.

### IF EITHER OIL PRESSURE OR FUEL PRESSURE SENSOR IS CONNECTED:

- 1. Set the slide switch to MPLAY.
- If the PLAY button is pressed, the gauge shifts to Playback mode and replays the data. The LED is blinking during Playback mode.



- 3. Set the slide switch to **UREAL** during playback (or pause).
- If the MOPEAK button is pressed during playback (or pause), the gauge displays the peak value (maximum value) of recorded data.
- 5. If the MOPEAK) button is pressed again, the gauge displays the peak value (minimum value) of recorded data. All the connected gauges except oil pressure and fuel pressure display maximum values.
- 6. If the MoPEAK button is pressed again, the gauge returns to playback of the data. To return to Real mode, set the slide switch to MPLAY and press long the PLAY button.

Data playback is ongoing during Play Peak mode.

# ■ Difference between Real peak, Rec peak, and Play peak

	Real peak	Rec peak	Play peak
Displayed in	Real mode	Record mode	Playback mode
Displayed value	Peak value in all	Peak value recorded in Record mode	
	modes		
Update of peak value	In all modes	During Record mo	de
Peak reset	Operatable in Real	Reset automatical	ly when recording
	peak mode	is started	



# 8 Troubleshooting

# ⚠ Warning

- If any indication of the problem is found in the product, check to make sure the product will operate as expected. Failure to do so can lead to serious accidents
- If any problem is found during using, setting or operating this product, use the following table to confirm proper operation of the unit. If the operational problem is not found in the following table, contact the installation personnel at the store where this product was purchased.

Condition	Possible Cause	Corrective Action
O Does not operate.	O Wiring of the power supply wire	○ Check wirings of +B, IGN,
O Power is not sup-	is improper.	GND as per instructions in
plied.	$\bigcirc$ The fuse of the power supply	this manual.
ODC Source LED of	wire is blown out.	○ Check wiring and replace
the control unit	○ The locks of the solderless con-	the fuse.
doesn't light.	nectors are not locked tightly.	○ Check the lock of the solder-
		less connectors.
ODC Source LED of	○ There is a wire short circuit or	Reconfirm the wiring and
the control unit is	disconnected wire somewhere.	the gauge according to
blinking.	Maybe there is something	operation manual. If any
	wrong on gauge.	defects are not found, please
		ask the shop for inspection.
○ Warning LED on	○ There is a wire short circuit or	Reconfirm the sensor and
gauge is blinking	disconnected wire somewhere	sensor wire according to
	on sensor or sensor wire. Maybe	operation manual. If any
	there is something wrong be-	defects are not found, please
	tween gauge and control unit.	ask the shop for inspection.



Condition	Possible Cause	Corrective Action
○ The illumination	○ The ILM wiring is improper.	○ Check wirings of ILM as per
of CR/RS gauges	○ The locks of the solderless con-	instructions in this manual.
is not lighted. The	nectors are not locked tightly.	○ Check the lock of the solder-
illumination of BF/	○ The illumination of gauge is set	less connectors.
A1 gauges is not	to off (illumination cancel).	Release illumination cancel
darkened.	○ The dimmer setting of ZD is	function as per instructions
	AUTO and vehicle is in bright	in this manual.
	light.	○ Change the dimmer setting
		to MANUAL or move vehicle
		to a dark place.
O Does not carry out the ending mode.	○ The battery wiring is improper.	<ul> <li>Check wiring of +B as per instructions in this manual.</li> <li>Check the solderless connector of battery wiring.</li> <li>Ask the store for inspection.</li> </ul>
○ The needle pointer is not around right under 0 before starting installation with power off.	The needle pointer moved in transit.	○ It is the unique feature of stepping motor that the needle pointer may move when a slight impact is made to the gauge with electricity off. Check if the needle pointer goes back to around 0 when the ignition is turned from on to off. If it does not, please contact the store or our customer service center.



Condition	Possible Cause	Corrective Action
○ The RPM is not displayed correctly.	Wiring of the tachometer signal is wrong.     Setting of the number of cylinders is wrong.	Corrective Action  Check wiring as per instructions in this manual.  Follow tachometer operation manual and wiring instruction for Speed & Tachometer signal wire to confirm the wiring.  Check the number of cylinders as per instructions in this manual.
This tachometer is reading slightly lower than the original tachometer.	○ Generally tachometer readings are about up to 10 %higher than actual RPM.	Check if the difference is up to 10%. This product is designed for high accuracy and should have little error margin. If the difference is much more than 10%, check setting of the number of cylinders.
Serial line error is displayed.	Communication error is occurred between gauges/ZDs and the control unit.	Check the meter wire as per instructions in this manual. If any defects are not found, please ask the shop for inspection.
Serial line errors are displayed on all the connected gauges.	<ul> <li>More than one pressure sensors(turbo, oil pressure, and fuel pressure) short-circuit.</li> </ul>	○ In case that the sensor is broken, it need to be changed. please ask the shop for inspection.



DF09501

# **9 Repair parts/Optional parts** AD:For ADVANCE system exclusive use

Parts Number	Repair Parts Name	
PDF07702H	AD Power supply wire (1m, 3 1/3ft)	
PDF07707H	AD Meter wire (0.25m, 10in)	
PDF07710H	AD Meter wire (2m, 6 3/5ft)	
PDF07807G	AD meter cup (52mm, 2 1/16in)	
PDF08606G	AD meter cup (60mm, 2 3/8in)	
PDF07809G	AD Installation parts for meter & ZD	
PDF07812G	AD Regular Position Bezel (52mm, 2 1/16in)	
PDF08607 G	AD Regular Position Bezel (60mm, 2 3/8in)	
PDF06503S	Turbo Sensor	
PDF00703S	Pressure Sensor	
PDF00903S	Temperature Sensor	
PDF01103S	Exhaust Temp. Sensor	
PDF01105G	Fitting for Exhaust Temp. Sensor	
PDF06505H	Turbo Sensor wire (2.5m, 8 1/5ft)	
PDF08105H	AD Oil Press. Sensor wire (3m, 10ft)	
PDF06603H	Fuel Press. Sensor wire (2.5m, 8 1/5ft)	
PDF05602H	Oil Temp. Sensor wire (3m, 10ft)	
PDF05603H	Water Temp. Sensor wire (3m, 10ft)	
PDF06803H	Exhaust Temp. Sensor wire (2.5m, 8 1/5ft)	
PDF09705H	AD Speed & Tachometer signal wire (2m, 6 3/5ft)	
PDF05005G	Fuse (4A) 2pcs	
Parts Number	Optional Parts Name	
PDF07708H	AD Meter wire(0.5m, 1 3/5ft)	
PDF07709H	AD Meter wire(1m, 3 1/3ft)	
PDF06002H	Turbo Sensor extension wire (1m, 3 1/3ft)	
PDF00707H	Pressure Sensor extension wire (2m, 6 3/5ft)	
PDF00906H	Temperature Sensor extension wire (2m, 6 3/5ft)	
PDF01107H	Exhaust Temp. Sensor extension wire (2m, 6 3/5ft)	
DF09601	ADVANCE Indicator	

<sup>\*</sup> For more information, contact our customer service center, or visit our website.

Fitting kit



### 10 Maintenance & Check/Warranty & Servicing

### ■ Warranty card • Terms and conditions

This product is delivered with this operation manual and a warranty card. Please read terms and conditions in this manual thoroughly and keep the warranty card in a safe place. Failure to show this warranty will void the warranty.

## ■ Warranty period

Limited one year warranty. The warranty period starts at the date of retail purchase by the original end-user purchase. Please confirm the warranty card is provided with the information of retail store where purchased. Please refer to Limited Warranty for details.

# **⚠** Warning

- ⚠ Except in the case of defects, we shall not be liable for any trouble including violation, accident or improper wiring resulting from using this product.
- The warranty does not cover any unauthorized repair performed or caused to be performed by the end user. Such action can destroy or damage this product.

### ■ Inspection

Please ask the shop you purchased the product for inspection if any defect in product is suspected. We don't accept the order of fixing because Defi products require installation and wiring to the vehicle.

In case you cannot go to the shop you purchased because of move-out or closure of shop, please ask the nearest Defi Distributor listed in the Defi website.

• For a repair/inspection service, take the warranty card and customer contact information with you.

Please conduct periodic inspections by Defi through a shop which sells Defi products or Defi's official distributor every five years. Inspection is available at an additional cost. In the case you purchase used proucts or used vehicles with products of Defi, please have an inspection by Defi as well before using them.



#### Customer contact information

Please provide the following information to a store representative when you ask for an inspection.

1. Your contact information
address, zip code:
name:
phone number:
email address:
Name and address of the store where purchased and installed.
3. Information about your vehicle
manufacture and car model:
model year:
vehicle type:
engine type:
engine displacement:
transmission (MT/AT):
speed limit canceller with without
genuine tachometer with without
engine swap with without
changing ignition device with without
changing ECU with without
the way to install the sensor:
other specification:
Your Defi products     (including the products that do not need inspection this time)
5. Describe your experience (when? do what?, what product? what happened? then what?)



#### ■ Label

The label stuck on the product is for tracing purposes. Do not peel it off.

# **■** Discarding the products

Please dispose products in accordance with disposal laws, state laws and local government requirements. A recycle label on the package indicates that the package is recyclable.



#### **Terms and Conditions**

LIMITED PRODUCT WARRANTY AND LIMITED PRODUCT LIABILITY

A. Limited Warranty

- a. Our sole obligation to you after the sale of a product is to replace, without charge, the product or any component thereof discovered to be defective within a period of one (1) year from the purchasing date(the "Warranty Period"). You accept sole responsibility for the proper assembly operation and regular maintenance of the product. This limited warranty is void if any product is damaged by accident, misuse, improper installation, or abuse, including tampering or damage in transit. Further, this limited warranty is void if you sell or otherwise transfer a product to a third party, regardless of whether the transfer takes place within the Warranty Period.
- b. Out liability to you resulting from the sale of any product, including liability for any latent defects found within the Warranty Period, shall not exceed the total purchase price paid for the product by you.
- c. YOU UNDERSTAND AND AGREE THAT WE MAKE NO REPRESENTATIONS OR WARRANTIES OF ANY KIND, EXPRESS OR IMPLIED AS TO ANY MATTER WHATSOEVER, INCLUDING THE CONDITION OF THE PRODUCT OR ANY COMPONENT PARTS THEREOF, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE AND YOU ACCEPT IT. "AS IS." "WHERE IS."
- d. You also understand that we are not granting any express warranties, other than those stated herein. These include only those warranties enumerated in paragraph A. a. There are no other express warranties granted anywhere in these terms and conditions of sale, and you understand and agree to this fact as part of the bargained for exchange of this sale. Nowhere else, except as stated in this paragraph, in this contract is there intended, by either party, for there to be any express warranties granted to you.
- e. EXCEPT AS OTHERWISE PROVIDED HEREIN, WE SHALL NOT BE LIABLE FOR DAMAGES, INCLUDING SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAM-AGES WHETHER IN CONTRACT OR IN TORT ARISING OUT OF OR IN CONNEC-TION WITH THE PERFORMANCE OF ANY PRODUCT OR ANY COMPONENT PART THEREOF OR ITS USE BY YOU, AND WE SHALL NOT BE LIABLE FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING OUT OF OR



#### IN CONNECTION WITH YOUR USE OF THE PRODUCT.

- f. The warranty on this product is void if the product is modified, changed, adjusted or damaged. This product is to be used only in the ways for which it is designed and marketed for, any deviations from the intended uses will void the warranty and will excuse any possible liability of ours.
- g. You accept sole responsibility for the proper assembly, operation and regular maintenance of the product. This limited warranty is void if the product is damaged, changed, altered, or modified by accident, misuse, improper installation, or abuse, including tampering or damage in transit or while in use. YOU HAVE MADE AN INDEPENDENT INVESTIGATION OF THE PURCHASED COMPONENTS AND HAVE RELIED SOLELY ON YOU OWN INVESTIGATION, BARGAINING AND JUDGMENT IN REFERENCE THERETO. YOU ACKNOWLEDGE THAT YOU ARE NOT RELYING ON OUR SKILL OR JUDGMENT TO SELECT OR FURNISH GOODS SUITABLE FOR ANY PARTICULAR PURPOSE IN PURCHASING OUR PRODUCTS, YOU HAVE NOT RELIED OR ACTED UPON ANY REPRESENTATIONS OR WARRANTIES ON OUR PART NOT SPECIFICALLY SET FORTH HEREIN
- h. This limited warranty gives you specific legal rights. You may also have other rights which vary from state to state. Some states do not enforce contractual limitations on how long an implied warranty lasts, when an action may be brought, or the exclusion or limitation of incidental or consequential damages, so the above limitations or exclusions may not apply to you.

### B. Modification Strictly Prohibited

You understand and agree that any modification whatsoever, of the product, is strictly prohibited. You also agree not to modify the product in any manner regardless of whether such modification is material or immaterial. You also acknowledge that any modification of the product will void your limited warranty and bar you from any recovery or any remedy in a court of law or equity. Modification is strictly forbidden unless expressly authorized by our prior written approval. You agree not to make any modifications to the product and agree not to use any parts, components, or accessories in connection with the installation and use of the product that are not authorized and approved by us.

### C. Indemnity and Release



- a. You understand and agree that many factors beyond our control affect the operational safety of the product, including but not to limited to the installation of the product according to the instructions provided with the product
- b. You also understand and agree that the installation of the product may involve the use of tools, equipment and construction methods which may present safety hazards which are beyond our control. You also understand and agree that the use of some of our products may create hazards and lower your ability to control your vehicle.
- c. You agree, as part of the bargained for exchange, to protect, indemnify, save harmless and release us, our authorized agents, employees, officers, directors and shareholders from and against all liabilities, obligations, claims, damages, penalties, causes of action, costs and expenses, imposed upon or incurred by or asserted against us or any assignees of ours, by you or any third party by reason of the occurrence or existence (or alleged occurrence or existence) of any use, installation, assembly, possession or operation of the product, any loss, damage or destruction of the product as of and after delivery(a "casualty occurrence"), and any other act or event relating to or caused by the product, including but not limited to, consequential or of the terms and conditions hereof, or any and all liability for property loss or damage, or any and all damage resulting from death or personal injuries, including loss of services which any person may sustain on account of, arising out of, or in connection with any use, maintenance, possession or operation of the product. In the event that any action, suit or proceeding is brought against us or any of our authorized agents, employees, officers, directors or shareholders by reason of any such occurrence, you will, upon our request and at your expense, resist and defend such action, suit or proceeding or cause the same to be resisted and defended by counsel designated and approved by us.







#### デフィーリンクアドバンス コントロールユニット取扱説明書

- ■発行 第3版2021年10月
- ■製造元 日本精機株式会社
- ■連絡先 日本精機株式会社 Defi お客様相談室

【住所】〒 940-8580 新潟県長岡市東蔵王 2 丁目 2-34 日本精機株式会社 Defi 【電話番号】(0258) 24-5221(Japanese only)

【受付時間】10:00~12:00, 13:00~17:00(土・日曜、祝日、当社休日を除く平日) 【Web サイト】https://www.nippon-seiki.co.jp/defi/

# **Defi-Link ADVANCE Control Unit Operation Manual**

- Issue 3rd edition: October, 2021
- Manufacturer Nippon Seiki Co., Ltd.
- Contact Information Defi, Nippon Seiki Co., Ltd.

  [Address] 2-34 Higashi-Zaoh 2-chome, Nagaoka-shi, Niigata 940-8580 JAPAN

  [URL] https://www.defi-shop.com/